

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 5938T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	1,560.00	1,560.00
1	REAR BUMPER CENTRE CHROME	NECESSARY	115.00	115.00
2	REAR BUMPER SIDE CHROME @\$110.00	NECESSARY	220.00	220.00
1	REAR BUMPER CENTRE BRACKET	CRACKED	149.00	149.00
2	REAR BUMPER SIDE BRACKET @\$80.00	NOT NECESSARY	160.00	-
2	REAR BUMPER SIDE RETAINER @\$48.00	DEFORMED	96.00	96.00
1	REAR BUMPER RE ENFORCEMENT	NOT NECESSARY	740.00	-
1	REAR END PANEL	NOT NECESSARY	1,376.00	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	242.00	-
1	SPARE TYRE BOTTOM COVER	NOT NECESSARY	298.00	-
	LESS 10% DISCOUNT		-495.60	-214.00
			4,460.40	1,926.00
	SPECIAL NETT ITEMS			
1	SET REVERSER SENSOR (SN)	DENTED	400.00	300.00
1	SET SPARE TYRE COVER SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET REAR END PANEL CLIPS (SN)	NOT NECESSARY	80.00	-
			660.00	330.00
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.		80.00	50.00
	TO RESET AND REPROGRAM AFTER REPAIR.		150.00	120.00
	TO R&R REAR LUGGAGE COMPARTMENT TRIMMING.	NOT NECESSARY	150.00	-
	TO CUT WEILD ON REAR END PANEL. TO PANEL BEAT AND STRAIGHTEN ON SPARE TYRE PANEL. TO R&R REAR BUMPER AND OTHER ATTACHMENTS.		1,000.00	300.00
	TO RESPRAY ON REAR BUMPER, BOOT LID, REAR END PANEL, REAR BOTH FENDERS AND ACCIDENT AFFECTED AREA.		1,000.00	400.00
	RUST PROOFING.		150.00	30.00
			2,530.00	900.00
	GRAND TOTAL		7,650.40	3,156.00

Report Ref No. CS3/HSB23006591/Rvp3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/HSB23006591/Rvp3e2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

P

**ANG BRYAN TANI** 

**Automotive Assessor / Investigator**