



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 1359P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LH HEADLAMP (WCP)	HOLDER CRACKED	1,150.00	1,150.00
1	FRT BUMPER (WCP)	DISTORTED	350.00	350.00
1	FRT BUMPER RETAINER LH (WCP)	BENT	55.00	55.00
10	FRT BUMPER CLIP (WCP)	NECESSARY	20.00	20.00
1	FRT LH FENDER (WCP)	BENT	330.00	330.00
1	FRT LH FENDER INNER COWLING (WCP)	SERVICEABLE	125.00	-
10	INNER COWLING CLIP (WCP)	NOT NECESSARY	20.00	-
1	FRT LH SHOCK ABSORBER (WCP)	NOT NECESSARY	230.00	-
1	FRT LH LOWER ARM (WCP)	NOT NECESSARY	295.00	-
1	FRT LH KNUCKLE ARM (WCP)	NOT NECESSARY	240.00	-
1	FRT LH KNUCKLE BEARING (WCP)	NOT NECESSARY	150.00	-
	COST PLUS 10%		296.50	190.50
			3,261.50	2,095.50
<u>SPECIAL NETT ITEMS</u>				
1	FRT LH SPORTS RIM (LOCAL REPAIR) (SN)	WARPED	150.00	150.00
			150.00	150.00
<u>LABOUR</u>				
	WIRE CHECKING.		30.00	20.00
	REMOVE & REFIX FRT UNDERCARRIAGE.	NOT NECESSARY	200.00	-
	4 WHEEL ALIGNMENT.		80.00	80.00
	LABOUR CHARGE.		600.00	500.00
	SPRAY PAINTING (PEARL). SPRAY WHEEL HOUSING PANEL.		700.00	700.00
			1,610.00	1,300.00
GRAND TOTAL			5,021.50	3,545.50



RECOMMENDED COST OF REPAIRS			3,545.50
LESS EXCESS			-500.00
NETT LIABILITY			3,045.50

Report Ref No. CS/GAI23006597/Uvp3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.