



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 2905J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,866.00	-
1	FRONT BUMPER LOGO	NOT NECESSARY	105.00	-
1	FRONT BUMPER PDC SENSOR O/S	NOT NECESSARY	225.00	-
1	SET FRONT BUMPER CLIPS	NOT NECESSARY	60.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	619.00	-
1	FRONT FENDER N/S	DENTED/BENT	915.00	681.00
1	FRONT FENDER INNER SHIELD N/S	TWISTED	288.00	242.00
1	SET FRONT FENDER INNER SHIELD CLIPS N/S	NECESSARY	50.00	50.00
1	FRONT SHOCK ABSORBER N/S	NOT NECESSARY	845.00	-
1	FRONT KNUCKLE ARM N/S	WARPED	1,255.00	645.00
1	FRONT WHEEL HUB BEARING N/S	DAMAGED	650.00	322.00
1	FRONT LOWER ARM N/S	BENT	920.00	562.00
1	FRONT DOOR N/S	TO REPAIR SEE LABOUR	2,201.00	-
1	FRONT DOOR INNER RUBBER N/S	NOT NECESSARY	280.00	-
1	SET FRONT DOOR FRAME STICKER N/S	NOT NECESSARY	60.00	-
	LESS 5% DISCOUNT		-	-125.10
			10,339.00	2,376.90
<u>SPECIAL NETT ITEMS</u>				
1	FRONT SPORT RIM N/S (SN)	WARPED	1,200.00	600.00
1	FRONT TYRE N/S (SN)	SERVICEABLE	250.00	-
			1,450.00	600.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED FRONT PDC SENSOR.		80.00	40.00
	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE.		180.00	120.00
	TO DISMANTLE & REFIX FRONT DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO RESET & DIAGNOSTIC SYSTEM.	NOT NECESSARY	200.00	-
	TO SPRAY RUST PROOFING.		100.00	30.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00

Report Ref No. CS/AGI23006634/Uqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT DOOR N/S. TO PUTTY & SPRAY PAINTING.		700.00	400.00
			1,000.00	600.00
			2,550.00	1,290.00
GRAND TOTAL			14,339.00	4,266.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CS/AGI23006634/Uqy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.