

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WC 4994S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT RH CORNER PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT RH CORNER PANEL BRACKET LH	DISTORTED	220.00	220.00
1	FRONT BUMPER	BENT	2,900.00	1,800.00
1	FRONT BUMPER OUTER RIM LH	DISTORTED	480.00	385.00
1	FRONT BUMPER LOWER BRACKET LH	BENT	220.00	132.50
1	FRONT BUMPER LAMP LH	CRACKED	385.00	385.00
1	HEADLAMP LH	MTG CRACKED	1,285.00	980.00
1	HEADLAMP INNER HOLDER BRACKET LH	TO REPAIR SEE LABOUR	980.00	-
1	SIGNAL LAMP LH	MTG CRACKED	580.00	185.00
1	FRONT LH STEP HOUSING TOP	BENT	980.00	980.00
1	FRONT LH STEP HOUSING CENTER RUBBER LH	DISTORTED	298.00	298.00
1	FRONT LH STEP HOUSING BOTTOM	BENT	1,485.00	850.00
2	STEP PANEL LH (TOP AND BOTTOM)	BENT (1PC ONLY)	800.00	328.00
1	FRONT STEP HOUSING LOWER SUPPORT	BENT	2,250.00	1,128.00
	LESS 15% DISCOUNT		-1,929.45	-1,150.73
			10,933.55	6,520.77
	<u>LABOUR</u>			
	LABOUR TO DO CUTTING, WELDING, REPAIR, REPLACE, ALIGN ADJUST ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT RH CORNER PANEL AND HEADLAMP INNER HOLDER BRACKET LH.		1,400.00	450.00
	TO DO ANTI RUST.	NOT NECESSARY	120.00	-
	TO CHECK WIRE SYSTEM, FORCUS HEADLAMP.		180.00	20.00
	TO DO SPRAY PAINTING ON ACCIDENT AREA (INNER & OUTER).		1,000.00	600.00
			2,700.00	1,070.00
	GRAND TOTAL		13,633.55	7,590.77



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		5,800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI23006637/Kvy3e2

KONG SENG CHEONG

Licensed Appraiser