

Hong Seh Motors Pte Ltd (Co.Reg.No:198203320D)10 Fourth Lok Yang Road, Jurong Town
Singapore 629707

Tel: 6266 1555 Fax: 6265 9595 Email: Shawnlee@hongseh.com.sg

INSURER: ERGO Insurance Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCG22014776	Date of Loss:	01/06/2023
Vehicle Reg. No.:	GBM782J	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CLEAN CITY(1995)PTE LTD		
Driver:	MUTHURAMALINGA SETHUPATHI PONK KOZHIYANDI		
Make/Model:	DFSK EC35, (A)	Vehicle Reg. Date:	19/10/2022
Vehicle Colour:	WHITE		
Engine No:	NIL	Chassis No:	LVP1PB4B2NC894027
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	31		
Present Location:	HONG SEH MOTORS PTE LTD (LOK YANG ROAD)		

COST OF CLAIMS

	Amount
Parts	43,834.75
Miscellaneous Items	450.00
Labour	5,120.00
Paintwork Labour	3,200.00
Towing	0.00
Gross Total (S\$)	52,604.75
+ GST 8.00% (S\$)	4,208.38
Nett Amount (S\$)	56,813.13

This claim is handled by: CHEN CHEE KIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Jun 2023)
 Parts: N/A DFSK EC35 (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hong Seh Motors Pte Ltd/GBM782J/30/06/2023 15:24
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT COVER <i>bt</i> BONNET	0.00	0.00	*243.69 F
2	1		*FRONT COVER HINGE LH <i>bt</i>	0.00	0.00	*24.00 F
3	1		*FRONT COVER HINGE RH <i>bt</i>	0.00	0.00	*24.00 F
4	1		*MID-FRONT ASSEMBLY	0.00	0.00	*3,820.20 F
5	1		*MID SECTION OF FRONT UPPER MEMBER <i>bt</i>	0.00	0.00	*2,654.20 F
6	2		*WELDED SQUARE NUT	0.00	0.00	*10.40 F
7	1		*Front welding assembly <i>bt</i>	0.00	0.00	*943.26 F
8	1		*Front pillar welding assembly (L) <i>bt</i>	0.00	0.00	*84.00 F
9	1		*Front pillar welding assembly (R) <i>bt</i>	0.00	0.00	*8.00 F
10	1		*Fender Assembly (L) <i>bt</i>	0.00	0.00	*199.01 F
11	1		*Fender Assembly (R) <i>bt</i>	0.00	0.00	*199.01 F
12	1		*Front wall panel (L) <i>repair</i>	0.00	0.00	*1,936.20 F
13	1		*Front panel side panel (R) ?	0.00	0.00	*657.50 F
14	1		*Front upper left component ?	0.00	0.00	*285.25 F
15	1		*Front upper component right segment ?	0.00	0.00	*285.25 F
16	1		*Lower corner panel of front wall panel (L) <i>bt</i>	0.00	0.00	*582.36 F
17	1		*Lower corner panel of front wall panel (R) <i>bt</i>	0.00	0.00	*582.36 F
18	1		*Accelerator pedal bracket assembly ?	0.00	0.00	*485.15 F
19	1		*Front wall panel assembly <i>repair</i>	0.00	0.00	*1,248.30 F
20	1		*Front wheel housing (L) ?	0.00	0.00	*32.39 F
21	1		*Front frame welding assembly ?	0.00	0.00	*1,582.35 F
22	1		*Front door welding assembly (L) ?	0.00	0.00	*468.30 F
23	1		*Front beam assembly ?	0.00	0.00	*74.63 F
24	1		*Hybrid headlight assembly (left) <i>bt</i>	0.00	0.00	*238.71 F
25	1		*Hybrid front lamp assembly (right) <i>bt</i>	0.00	0.00	*238.71 F
26	1		*Front fog lamp assembly (right) <i>cm</i>	0.00	0.00	*119.91 F
27	1		*Front fog lamp assembly (left) <i>cm</i>	0.00	0.00	*119.91 F
28	1		*Harness gp-cab ?	0.00	0.00	*647.61 F
29	1		*Harness gp-chassis ?	0.00	0.00	*1,073.99 F
30	1		*High voltage harness assembly ?	0.00	0.00	*422.39 F
31	1		*High voltage distribution box ?	0.00	0.00	*1,619.01 F
32	1		*Electric control connecting line ?	0.00	0.00	*450.51 F
33	1		*Combination switch, front fog lamp, no rear wiper X	0.00	0.00	*44.97 F
34	1		*Front wiper link X	0.00	0.00	*14.79 F
35	1		*Front wiper motor and bracket assembly X	0.00	0.00	*43.08 F
36	1		*Washer water storage tank and motor (single motor) X	0.00	0.00	*12.00 F
37	1		*Electronic flasher	0.00	0.00	*9.15 F
38	1		*Tweeter(horn) X	0.00	0.00	*14.64 F
39	1		*Pedestrian warning device (ABS) <i>cm</i>	0.00	0.00	*211.17 F
40	1		*Motor controller assembly	0.00	0.00	*3,416.36 F
41	1		*Vehicle controller ?	0.00	0.00	*724.44 F
42	1		*Front evaporator assembly ?	0.00	0.00	*263.54 F
43	1		*Compressor and controller assembly ?	0.00	0.00	*1,370.30 F
44	1		*Compressor discharge connection pipe ?	0.00	0.00	*60.60 F

Hong Seh Motors Pte Ltd/GBM782J/30/06/2023 15:24. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

23, 3:45 PM

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*Tube gp-coupling ?	0.00	0.00	
46	1		*Compressor inlet connection pipe ?	0.00	0.00	*30.04 F
47	1		*Condenser assembly lt ✓	0.00	0.00	*56.32 F
48	1		*Radiator Assy	0.00	0.00	*274.62 F
49	1		*Reservoir assy X	0.00	0.00	*343.42 F
50	1		*Upper radiator bracker Rh lt ✓	0.00	0.00	*38.30 F
51	1		*Upper radiator bracker lt ✓	0.00	0.00	*20.25 F
52	1		*Radiator Bracket Assy lt ✓	0.00	0.00	*20.25 F
53	1		*Feed Nozzle X	0.00	0.00	*65.32 F
54	1		*Radiator Fan Motor Assy X	0.00	0.00	*18.80 F
55	1		*Water Pump X	0.00	0.00	*150.17 F
56	1		*Front Shock absorber Assy Left ?	0.00	0.00	*150.17 F
57	1		*Front Shock absorber Assy Right ?	0.00	0.00	*274.52 F
58	1		*Front sway arm assy. LHD ?	0.00	0.00	*274.52 F
59	1		*Front sway arm assy. RHD ?	0.00	0.00	*51.15 F
60	1		*Front Suspension Cross-member ?	0.00	0.00	*51.15 F
61	1		*Front Stabilizer ?	0.00	0.00	*183.15 F
62	1		*Front Stabilizer Bracket ?	0.00	0.00	*322.20 F
63	1		*Stabilizer Assy (link) ?	0.00	0.00	*35.00 F
64	1		*Steering Gear Assy. ?	0.00	0.00	*245.52 F
65	1		*Lower Steering shaft ?	0.00	0.00	*255.75 F
66	1		*Tie-rod and Ball Joint LHD ?	0.00	0.00	*265.20 F
67	1		*Tie-rod and Ball Joint RHD ?	0.00	0.00	*57.25 F
68	1		*brake Pump with vaccum boost X	0.00	0.00	*57.25 F
69	1		*Electric Vaccum Pump Assy. ?	0.00	0.00	*294.25 F
70	1		*Vacuum reservoir assembly ?	0.00	0.00	*938.55 F
71	2		*Front Brake Tube	0.00	0.00	*69.82 F
72	1		*ABS Executor Assy ?	0.00	0.00	*30.50 F
73	1		*Front Wheel Sensor Assy.LHD ?	0.00	0.00	*1,036.40 F
74	1		*Front Wheel Sensor Assy. RHD ?	0.00	0.00	*50.45 F
75	1		*wiper Trim cut ✓	0.00	0.00	*50.45 F
76	1		*Front bumper assembly turn ✓	0.00	0.00	*22.70 F
77	1		*Front bumper mounting bracket (left) cm ✓	0.00	0.00	*330.74 F
78	1		*Front bumper mounting bracket (right) cm ✓	0.00	0.00	*28.30 F
79	1		*Front Bumper MIDDLE grille cm ✓	0.00	0.00	*28.30 F
80	1		*hood lock lt ✓	0.00	0.00	*107.70 F
81	1		*Hood lock release cable X	0.00	0.00	*64.60 F
82	1		*Front grille cm ✓	0.00	0.00	*35.20 F
83	1		*Front seat belt buckle assembly (right) X	0.00	0.00	*154.85 F
84	1		*Front seat belt buckle assembly (left) X	0.00	0.00	*103.25 F
85	1		*Front seat belt body assembly (right) X	0.00	0.00	*103.25 F
86	1		*Front seat belt body assembly (left) X	0.00	0.00	*100.90 F
87	1		*Front logo assembly re ✓	0.00	0.00	*100.90 F
88	1		*Driver air bag air ✓	0.00	0.00	*35.00 F
89	1		*Front Air bag sensor Lh air ?	0.00	0.00	*2,252.55 F
90	1		*Front Air Bag Sensor Rh ?	0.00	0.00	*205.83 F
91	1		*WHEEL CAP X	0.00	0.00	*205.83 F
92	1		*Upper body of instrument panel ?	0.00	0.00	*24.97 F
93	1		*FRONT MEMBER STRINGER LH ?	0.00	0.00	*150.16 F
94	1		*FRONT MEMBER STRINGER RH ?	0.00	0.00	*350.00 F
95	1		*FRONT LEFT FENDER LINING di ✓	0.00	0.00	*350.00 F
96	1		*FRONT RIGHT FENDER LINING di ✓	0.00	0.00	*32.90 F
97	20		*FRONT FENDER LINING CLIP re ✓	0.00	0.00	*32.90 F
				0.00	0.00	*40.00 F

F=Franchise part.

Sub Total (S\$) 38,117.17
+ Margin on L,N Items 15.00% (S\$) 5,717.58

Total Parts (S\$) 43,834.75

Hong Seh Motors Pte Ltd/GBM782J/30/06/2023 15:24. Not valid without Reference section.
Generated using Merlimen e-Claims IEAS

<https://singapore.merlimen.com/claims/index.cfm?cfm=...>

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	Air-cond gas (R134A) <i>h/s</i>		
2	4	BRAKE FLUID <i>h/s</i>	100	120.00
3	2	COOLANT <i>h/s</i>	20	140.00
4	1	FRONT NUMBER PLATE <i>cm</i>	50	70.00
		WITH HOLDER	35	50.00
5	1	Road wheel alignment		35.00
6	1	Road wheel balancing		35.00
Sub Total (\$\$)				450.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	Respray premier and paint front bumper, bonnet, both fender, front panel, hood base, front both door and engine base	New	2800	3,200.00
---	--	-----	------	----------

480x6

Labour Items

2	Remove, replace and realign with panel beating bonnet, fender, front panel, hood base, front door, headlamp panel and chassis realign	New	2500	3,000.00
3	Mount vehicle on chassis alignment bench and rectify chassis to recommend specification	New		600.00
4	Secure security area for electrical vehicle with diagnosis tools and release current	New	800	1,400.00
5	Process brake beelding after replacement brake master pump	New		60.00
6	Air cond system checking	New		60.00

Gross Labour Cost (\$\$) 8,320.00

Hong Seh Motors Pte Ltd/GBM782J/30/06/2023 15:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Faru
Hp 90210068
14 days
7/p
04/07/23
EXCESS: 2500
Revised
Resuy before paint