

(08/11/13) wef

ASS. REC. BY: gme

REF:

CS/EG/123006640/Rng3

538c

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBM 782Jat Workshop m/s HONG SEH MOTORof 10, FRANKLIN LANE, LKInsured: EG

Policy No.

Claims No.

Sum Insured:

Excess: 2000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

110K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBM 782J

Yr Regn:

04 1262BType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

PEPSK EC 31

C.C.

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LVPIPB4B2NLC894027Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXPREK

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

01/06/23

D.O.I.

04/07/23

Survey held at

HONG SEH MOTORDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 80K

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

Hong Seh Motors Pte Ltd (Co.Reg.No:198203320D)10 Fourth Lok Yang Road, Jurong Town
Singapore 629707

Tel: 6266 1555 Fax: 6265 9595 Email: Shawnlee@hongseh.com.sg

INSURER: ERGO Insurance Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCG22014776	Date of Loss:	01/06/2023
Vehicle Reg. No.:	GBM782J	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CLEAN CITY(1995)PTE LTD		
Driver:	MUTHURAMALINGA SETHUPATHI PONK KOZHIYANDI		

Make/Model:	DFSK EC35, (A)	Vehicle Reg. Date:	19/10/2022
Vehicle Colour:	WHITE		
Engine No:	NIL	Chassis No:	LVP1PB4B2NC894027
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	31

Present Location:	HONG SEH MOTORS PTE LTD (LOK YANG ROAD)
-------------------	---

COST OF CLAIMS

	Amount
Parts	43,834.75
Miscellaneous Items	450.00
Labour	5,120.00
Paintwork Labour	3,200.00
Towing	0.00

Gross Total (S\$)	52,604.75
+ GST 8.00% (S\$)	4,208.38
Nett Amount (S\$)	56,813.13

This claim is handled by: CHEN CHEE KIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Jun 2023)
 Parts: N/A DFSK EC35 (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hong Seh Motors Pte Ltd/GBM782J/30/06/2023 15:24
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT COVER <i>bt</i> BONNET	0.00	0.00	*243.69 F
2	1		*FRONT COVER HINGE LH <i>bt</i>	0.00	0.00	*24.00 F
3	1		*FRONT COVER HINGE RH <i>bt</i>	0.00	0.00	*24.00 F
4	1		*MID-FRONT ASSEMBLY	0.00	0.00	*3,820.20 F
5	1		*MID SECTION OF FRONT UPPER MEMBER <i>bt</i>	0.00	0.00	*2,654.20 F
6	2		*WELDED SQUARE NUT	0.00	0.00	*10.40 F
7	1		*Front welding assembly <i>bt</i>	0.00	0.00	*943.26 F
8	1		*Front pillar welding assembly (L) <i>bt</i>	0.00	0.00	*84.00 F
9	1		*Front pillar welding assembly (R) <i>bt</i>	0.00	0.00	*8.00 F
10	1		*Fender Assembly (L) <i>bt</i>	0.00	0.00	*199.01 F
11	1		*Fender Assembly (R) <i>bt</i>	0.00	0.00	*199.01 F
12	1		*Front wall panel (L) <i>repair</i>	0.00	0.00	*1,936.20 F
13	1		*Front panel side panel (R) ?	0.00	0.00	*657.50 F
14	1		*Front upper left component ?	0.00	0.00	*285.25 F
15	1		*Front upper component right segment ?	0.00	0.00	*285.25 F
16	1		*Lower corner panel of front wall panel (L) <i>bt</i>	0.00	0.00	*582.36 F
17	1		*Lower corner panel of front wall panel (R) <i>bt</i>	0.00	0.00	*582.36 F
18	1		*Accelerator pedal bracket assembly ?	0.00	0.00	*485.15 F
19	1		*Front wall panel assembly <i>repair</i>	0.00	0.00	*1,248.30 F
20	1		*Front wheel housing (L) ?	0.00	0.00	*32.39 F
21	1		*Front frame welding assembly ?	0.00	0.00	*1,582.35 F
22	1		*Front door welding assembly (L) ?	0.00	0.00	*468.30 F
23	1		*Front beam assembly ?	0.00	0.00	*74.63 F
24	1		*Hybrid headlight assembly (left) <i>bt</i>	0.00	0.00	*238.71 F
25	1		*Hybrid front lamp assembly (right) <i>bt</i>	0.00	0.00	*238.71 F
26	1		*Front fog lamp assembly (right) <i>cm</i>	0.00	0.00	*119.91 F
27	1		*Front fog lamp assembly (left) <i>cm</i>	0.00	0.00	*119.91 F
28	1		*Harness gp-cab ?	0.00	0.00	*647.61 F
29	1		*Harness gp-chassis ?	0.00	0.00	*1,073.99 F
30	1		*High voltage harness assembly ?	0.00	0.00	*422.39 F
31	1		*High voltage distribution box ?	0.00	0.00	*1,619.01 F
32	1		*Electric control connecting line ?	0.00	0.00	*450.51 F
33	1		*Combination switch, front fog lamp, no rear wiper X	0.00	0.00	*44.97 F
34	1		*Front wiper link X	0.00	0.00	*14.79 F
35	1		*Front wiper motor and bracket assembly X	0.00	0.00	*43.08 F
36	1		*Washer water storage tank and motor (single motor) X	0.00	0.00	*12.00 F
37	1		*Electronic flasher	0.00	0.00	*9.15 F
38	1		*Tweeter(horn) X	0.00	0.00	*14.64 F
39	1		*Pedestrian warning device (ABS) <i>cm</i>	0.00	0.00	*211.17 F
40	1		*Motor controller assembly	0.00	0.00	*3,416.36 F
41	1		*Vehicle controller ?	0.00	0.00	*724.44 F
42	1		*Front evaporator assembly ?	0.00	0.00	*263.54 F
43	1		*Compressor and controller assembly ?	0.00	0.00	*1,370.30 F
44	1		*Compressor discharge connection pipe ?	0.00	0.00	*60.60 F

Hong Seh Motors Pte Ltd/GBM782J/30/06/2023 15:24. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1	*Tube gp-coupling ?	0.00	0.00	*30.04 F
46	1	*Compressor inlet connection pipe ?	0.00	0.00	*56.32 F
47	1	*Condenser assembly st ✓	0.00	0.00	*274.62 F
48	1	*Radiator Assy	0.00	0.00	*343.42 F
49	1	*Reservoir assy X	0.00	0.00	*38.30 F
50	1	*Upper radiator bracker Rh st ✓	0.00	0.00	*20.25 F
51	1	*Upper radiator bracker Lh st ✓	0.00	0.00	*20.25 F
52	1	*Radiator Bracket Assy st ✓	0.00	0.00	*65.32 F
53	1	*Feed Nozzle X	0.00	0.00	*18.80 F
54	1	*Radiator Fan Motor Assy X	0.00	0.00	*150.17 F
55	1	*Water Pump X	0.00	0.00	*150.17 F
56	1	*Front Shock absorber Assy Left ?	0.00	0.00	*274.52 F
57	1	*Front Shock absorber Assy Right ?	0.00	0.00	*274.52 F
58	1	*Front sway arm assy. LHD ?	0.00	0.00	*51.15 F
59	1	*Front sway arm assy. RHD ?	0.00	0.00	*51.15 F
60	1	*Front Suspension Cross-member ?	0.00	0.00	*183.15 F
61	1	*Front Stabilizer ?	0.00	0.00	*322.20 F
62	1	*Front Stabilizer Bracket ?	0.00	0.00	*35.00 F
63	1	*Stabilizer Assy (link) ?	0.00	0.00	*245.52 F
64	1	*Steering Gear Assy. ?	0.00	0.00	*255.75 F
65	1	*Lower Steering shaft ?	0.00	0.00	*265.20 F
66	1	*Tie-rod and Ball Joint LHD ?	0.00	0.00	*57.25 F
67	1	*Tie-rod and Ball Joint RHD ?	0.00	0.00	*57.25 F
68	1	*brake Pump with vaccum boost X	0.00	0.00	*294.25 F
69	1	*Electric Vaccum Pump Assy. ?	0.00	0.00	*938.55 F
70	1	*Vacuum reservoir assembly ?	0.00	0.00	*69.82 F
71	2	*Front Brake Tube	0.00	0.00	*30.50 F
72	1	*ABS Executor Assy ?	0.00	0.00	*1,036.40 F
73	1	*Front Wheel Sensor Assy.LHD ?	0.00	0.00	*50.45 F
74	1	*Front Wheel Sensor Assy. RHD ?	0.00	0.00	*50.45 F
75	1	*wiper Trim cut ✓	0.00	0.00	*22.70 F
76	1	*Front bumper assembly torn ✓	0.00	0.00	*330.74 F
77	1	*Front bumper mounting bracket (left) cm ✓	0.00	0.00	*28.30 F
78	1	*Front bumper mounting bracket (right) cm ✓	0.00	0.00	*28.30 F
79	1	*Front Bumper MIDDLE grille cm ✓	0.00	0.00	*107.70 F
80	1	*hood lock st ✓	0.00	0.00	*64.60 F
81	1	*Hood lock release cable X	0.00	0.00	*35.20 F
82	1	*Front grille cm ✓	0.00	0.00	*154.85 F
83	1	*Front seat belt buckle assembly (right) X	0.00	0.00	*103.25 F
84	1	*Front seat belt buckle assembly (left) X	0.00	0.00	*103.25 F
85	1	*Front seat belt body assembly (right) X	0.00	0.00	*100.90 F
86	1	*Front seat belt body assembly (left) X	0.00	0.00	*100.90 F
87	1	*Front logo assembly ✓	0.00	0.00	*35.00 F
88	1	*Driver air bag AT ✓	0.00	0.00	*2,252.55 F
89	1	*Front Air bag sensor Lh st ?	0.00	0.00	*205.83 F
90	1	*Front Air Bag Sensor Rh ?	0.00	0.00	*205.83 F
91	1	*WHEEL CAP X	0.00	0.00	*24.97 F
92	1	*Upper body of instrument panel ?	0.00	0.00	*150.16 F
93	1	*FRONT MEMBER STRINGER LH ?	0.00	0.00	*350.00 F
94	1	*FRONT MEMBER STRINGER RH ?	0.00	0.00	*350.00 F
95	1	*FRONT LEFT FENDER LINING di ✓	0.00	0.00	*32.90 F
96	1	*FRONT RIGHT FENDER LINING di ✓	0.00	0.00	*32.90 F
97	20	*FRONT FENDER LINING CLIP ✓	0.00	0.00	*40.00 F

F=Franchise part.

Sub Total (\$\$) 38,117.17
+ Margin on L,N Items 15.00% (\$\$) 5,717.58

Total Parts (\$\$) 43,834.75

Hong Seh Motors Pte Ltd/GBM782J/30/06/2023 15:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Air-cond gas (R134A) <i>h</i>	
2	4	BRAKE FLUID <i>m</i>	100 120.00
3	2	COOLANT <i>m</i>	20 140.00
4	1	FRONT NUMBER PLATE <i>ca</i>	50 20.00
		WITH HOLDER	35 50.00
5	1	Road wheel alignment	35.00
6	1	Road wheel balancing	35.00
Sub Total (S\$)			450.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Respray premier and paint front bumper, bonnet, both fender, front panel, hood base, front both door and engine base <i>480x6</i>	New 2800	3,200.00
<u>Labour Items</u>			
2	Remove, replace and realign with panel beating bonnet, fender, front panel, hood base, front door, headlamp panel and chassis realign	New 2500	3,000.00
3	Mount vehicle on chassis alignment bench and rectify chassis to recommend specification	New	600.00
4	Secure security area for electrical vehicle with diagnosis tools and release current	New 800	1,400.00
5	Process brake beelding after replacement brake master pump	New	60.00
6	Air cond system checking	New	60.00
Gross Labour Cost (S\$)			8,320.00

Hong Seh Motors Pte Ltd/GBM782J/30/06/2023 15:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Same
Hp 90210068
14 days
7/P
04/07/23
Excess: 2500
Reuser
Resuy before print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

Total Rebate Amount:

Message

Transfer of ownership or deregistration is not allowed for this vehicle.

The information contained herein is correct as at 05 Jun 2023

Company

535C

GBM782J

Yes

05 Jun 2023

DFSK

EC31

White

2022

-

LVP1PB4B2NC894027

-

\$26,441.00

19 Oct 2022

19 Oct 2022

0

\$1,323.00

No

-

\$0.00

18 Oct 2032

C - Goods Vehicle & Bus

10

\$36,399.00

\$29,119.00

\$29,119.00

OK



DFSK EC31 Electric

\$111,666 Instalment \$1,481/mth

PREMIUM AD

Shortlist

Loan Calculator



Overview Financial Photo Research

Depreciation

\$11,870 / year

Reg. Date

30-Nov-2022

(9yrs 4mths 24days COE left)

Lifespan

29-Nov-2042

Manufactured

2022

Mileage

21,142 km

Transmission

Auto

Curb Weight

1,520 kg

Fuel Type

Electric

COE

\$42,902

OMV

\$26,441

ARF

\$1,323

Dereg Value

\$40,375 as of today

No. of Owners

1

Type of Veh

Van

Features