

Upon reinspection, surveyor did a test on the
brake. found out brake is on working condition. No defect at all.
Brake fluid is at its level. No sign of leaking.