

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123006641/UNY3Q2**Date:** 18/07/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SJL6073T **Insured Vehicle No :** SKK8617E

Date of Loss: 02/07/2023 Nature of Claim: TP Claim No: CDMPG23001608

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJL6073T**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 3ZZ4807043

Reg. Date: 04/12/2008 (Man. Year: 2008) Chassis No: MR053ZEE106122228

Colour: Grey Odometer: 179864 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,128.30	2,328.62	5,799.68	71.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,940.00	1,110.00	36.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,178.30	4,268.62	6,909.68	61.81
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	11,178.30	3,400.00	7,778.30	69.58
+ GST 8.00/8.00% (S\$)	894.26	272.00	622.26	69.58
Nett Amount (S\$)	12,072.56	3,672.00	8,400.56	69.58

INSPECTION

Date of Assignment: 03/07/2023

Date Inspected: 03/07/2023 Inspected At: Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL6073T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,266.10 F	*- FL
2	1		*BOOTLID REAR LOGO	Necessary	68.50 F	*68.50 FL
3	1		*BOOTLID COROLLA EMBLEM	Necessary	62.80 F	*62.80 FL
4	1		*BOOTLID ALTIS EMBLEM	Necessary	58.00 F	*58.00 FL
5	1		*BOOTLID 1.6 EMBLEM	Necessary	38.00 F	*38.00 FL
6	1		*BOOTLID INNER LOCK	Not Necessary	409.10 F	*- FL
7	1		*BOOTLID LOCK STRICKER	Not Necessary	66.80 F	*- FL
8	1		*BOOTLID WEATHERSTRIP	Twisted	282.30 F	*282.30 FL
9	1		*REAR BUMPER	Dented / Deformed	655.10 F	*655.10 FL
10	1		*REAR BUMPER SPONGE	Torn	505.40 F	*288.20 FL
11	1		*REAR BUMPER BRACKETS	N/S Dented / O/S Serviceable	210.00 F	*105.00 FL
12	2		*REAR BUMPER REFLECTORS	Not Necessary	120.00 F	*- FL
13	2		*REAR BUMPER SIDE RETAINERS	Necessary	130.00 F	*130.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	1		*REAR END PANEL	Dented / Bent	788.20 F	*645.10 FL
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	362.30 F	*- FL
17	1		*TAILLAMPS	N/S Not Necessary / O/SCracked	1,160.00 F	*388.50 FL
18	1		*REAR FLOOR PANEL	Repair	1,145.20 F	*- FL
19	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	420.50 F	*- FL
20	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
21	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,128.30	3,021.50
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	692.88
Total Parts (\$\$)	8,128.30	2,328.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	40.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,100.00	850.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (S\$)			3,050.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >