



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 6803A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR NO.PLATE (SN)	DENTED	60.00	25.00
2	REAR NO.PLATE LAMPS (SN)	DENTED	300.00	300.00
1	60KM/H STICKER (SN)	NECESSARY	30.00	15.00
1	REAR CARRIAGE END PANEL (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
			390.00	340.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO DO CUTTING, REPAIR, REPLACE ACCIDENT AFFECTED AREA.		600.00	80.00
	ANTI RUST.	NOT NECESSARY	120.00	-
	TO DO SPRAY PAINTING WORK.		600.00	250.00
			1,320.00	330.00
GRAND TOTAL			1,710.00	670.00

RECOMMENDED COST OF REPAIRS			670.00
------------------------------------	--	--	---------------

Report Ref No. CS/AGI23006702/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.