



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBT 3915L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	AXLE FRONT RIM	BENT	45.00	45.00
1	BALL STERRING CONE STEEL 8X18	NECESSARY	15.00	15.00
1	BAR HANDLE	BENT	68.00	68.00
1	BOLT CAP 6*16	CUT	9.00	9.00
1	COVER FRONT RH	CUT	54.00	54.00
1	COVER FRONT RH TOP	CUT	108.00	108.00
1	COVER RH FUEL TANK	CUT	154.00	154.00
1	COWLING FRONT	CUT	64.00	64.00
1	COWLING RH MIDDLE	CUT	58.00	58.00
1	CROWN HANDLE	NOT NECESSARY	168.00	-
1	EMBLEM HONDA 65MM	NECESSARY	45.00	45.00
1	EMBLEM RH WING 80MM	NECESSARY	45.00	45.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	1,644.00	-
1	FORK LH ASSY	BENT	707.00	707.00
1	FORK RH ASSY	BENT	707.00	707.00
1	FOTREST REAR RH	CUT	36.00	36.00
1	HANDLE GUARD RH	CUT	32.00	32.00
1	HEADLAMP ASSY	CRACKED	400.00	400.00
1	LEVER BRAKE	CUT	26.00	26.00
1	MIRROR RH	CUT	35.00	35.00
1	MUDGUARD FRONT A	CUT	68.00	68.00
1	MUDGUARD FRONT B	CUT	54.00	54.00
1	PEDAL BRAKE	BENT	58.00	58.00
1	PROTECTOR EXHAUST	CUT	85.00	85.00
1	STAY FRONT COWLING	BENT	102.00	102.00
1	STAY RH HANDLE GUARD	BENT	68.00	68.00
1	SET STEERING CONE	NECESSARY	55.00	55.00
1	STICKER COMBI BRAKE TOPPER	NECESSARY	24.00	24.00
1	STICKER COVER RH FUEL TANK	NECESSARY	32.00	32.00
1	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	NECESSARY	30.00	30.00

Report Ref No. CS/SMR23006705/Uqy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	UNDER FORK BRACKET	BENT	262.00	262.00
1	WINDSHIELD	SCRATCHED	988.00	988.00
	LESS 10% DISCOUNT		-	-443.40
			6,246.00	3,990.60
	<b>LABOUR</b>			
	LABOUR QUOTED FOR DISMANTLING & INSTALLATION OF PARTS. INCLUSIVE OF THE REPAIR OF EXHAUST ASSY.		1,032.00	450.00
			1,032.00	450.00
<b>GRAND TOTAL</b>			<b>7,278.00</b>	<b>4,440.60</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,440.60</b>

Report Ref No. CS/SMR23006705/Uqy3m4

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.