

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23006708/UVY3E2**Date:** 21/07/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001920667

**Claimant Vehicle No :** GBH1860L**Insured Vehicle No :** SJV5611U

Date of Loss: 23/06/2023

Nature of Claim: TP Claim No: 320669

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBH1860L**

Make &amp; Model: TOYOTA HIACE, 3.0 D DX (A)

Engine No: 1KD2778971

Reg. Date: 07/03/2018 (Man. Year: 2017)

Chassis No: KDH2010240098

Colour: Silver

Odometer: 107762 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,846.47	3,464.80	4,381.67	55.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,770.00	1,660.00	2,110.00	55.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,616.47</b>	<b>5,124.80</b>	<b>6,491.67</b>	<b>55.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,616.47</b>	<b>4,000.00</b>	<b>7,616.47</b>	<b>65.57</b>

INSPECTION

Date of Assignment: 04/07/2023

Date Inspected: 04/07/2023 Inspected At:

Euro Success Services Pte Ltd (HQ)  
1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>		(Last Synchronised: 07 Jul 2023)
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 D DX (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH1860L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Badly Dented / Bent	2,067.00 FL	*2,067.00 FL
2	2		*REAR TAIL GATE STOPPER	Not Necessary	50.00 FL	*- FL
3	2		*REAR TAIL GATE DAMPER	Not Necessary	450.00 FL	*- FL
4	1		*REAR TAIL GATE WEATHERSTRIP	Not Necessary	405.00 FL	*- FL
5	2		*REAR TAIL GATE CORNER GARNISH	Not Necessary	60.00 FL	*- FL
6	1		*REAR TAIL GATE OUTER MOULDING	Not Necessary	328.00 FL	*- FL
7	1		*REAR TAIL GATE LOCK MOTOR	Not Necessary	542.00 FL	*- FL
8	1		*REAR TAIL GATE INNER LOCK	Damaged	285.60 FL	*285.60 FL
9	1		*REAR TAIL GATE LOWER LOCK	Not Necessary	49.50 FL	*- FL
10	1		*REAR TAIL GATE INNER TRIM BOARD	Not Necessary	295.60 FL	*- FL
11	1		*REAR TAIL GATE WIPER ARM	Not Necessary	172.00 FL	*- FL
12	1		*REAR TAIL GATE WINDSCREEN MOULDING	No such part	362.00 FL	*- FL
13	1		*REAR TAIL LAMP	N/S NotNecessary / O/S Cracked	824.00 FL	*386.00 FL
14	2		*REAR TAIL LAMP LOWER GARNISH	Repair	498.60 FL	*- FL
15	1		*REAR BUMPER	Deformed	486.30 FL	*486.30 FL
16	1		*REAR BUMPER L-R RETAINER	N/S Not Necessary O/S Bent	120.00 FL	*60.00 FL
17	1		*REAR BUMPER STEP PANEL REINFORCEMENT	Bent	284.30 FL	*284.30 FL
18	1		*REAR END PANEL - OUTER	Dented / Bent	597.20 FL	*597.20 FL
19	1		*REAR END PANEL - INNER	Repair	871.20 FL	*- FL
20	1		*REAR TAIL GATE TRIMBOARD CLIP	Not Necessary	50.00 FS	*- FS
21	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
22	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	60.00 FS	*- FS
23	1		*REAR TAIL GATE LOGO	Necessary	93.00 FS	*50.00 FS
24	1		*REAR TAIL GATE HIACE STICKER	Not Necessary	40.00 FS	*- FS
25	1		*REAR TAIL GATE REAR TAIL GATE 70 STICKER	Necessary	30.00 FS	*10.00 FS
26	1		*REAR TAIL GATE 8 PAX STICKER	Necessary	30.00 FS	*10.00 FS
27	1		*SET REAR BUMPER SENSOR	Cracked	450.00 FS	*200.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	90.00 FS	*40.00 FS
29	1		*REAR TAIL GATE WIPER MOTOR	Not Necessary	523.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,164.30</b>	<b>4,506.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,317.83	1,041.60
<b>Total Parts (\$\$)</b>	<b>7,846.47</b>	<b>3,464.80</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER REAR TAILGATE MECHANISM	New	300.00	60.00
2	TO CHECK ELECTRICAL WIRING	New	120.00	20.00
3	TO APPLY UNDERCOATING ON ACCIDENT PARTS	New	250.00	60.00
4	TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	200.00	120.00
5	TO RESPRAY PAINTING	New	1,300.00	600.00
6	PANEL BEATING, CUT, WELD REAR PANEL TAILGATE AND REPLACING ABOVE PARTS	New	1,600.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,770.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >