

(08/11/13)

Wet

ASS. REC. BY: 7

REF:

CS3/SPF 2300 6719/Ring 3

3496

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBL 6393P

at Workshop m/s

ENG SOON

of

Yen Tee

Insured:

SPF

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

92K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

REPAIR LIMIT - 65K

Veh No:

GBL 6393PYr Regn: 2021 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA HIACE DX 2.0 Ac.c. 1998

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

30151

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TR4205048364

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

P15/80R15

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

26/06/23

D.O.I.

10/07/23

Survey held at

ENG SOON

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report

Days Of Repair:

1)



: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393-J
Woodlands Road
Singapore 677978
Tel: 67606271 Fax: 67646676

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 26/06/2023

Attn: Motor Claim Dept

Repair cost of TOYOTA HIACE COMMUTER GL – GBL6393P

SN	DESCRIPTION	AMOUNT
1	Rear bumper <i>de /</i>	\$ 688.40
2	Rear bumper retainer LH & RH <i>X</i>	\$ 116.40
3	Rear bumper lower bracket (4x) <i>X</i>	\$ 118.40
4	Rear end panel outer <i>repar</i>	\$ 580.40
5	Rear end panel top plate <i>repar X</i>	\$ 198.00
6	Tailgate <i>bl /</i>	\$ 2,250.00
7	Tailgate 'LOGO' emblem <i>re /</i>	\$ 72.70
8	Tailgate 'HIACE' emblem <i>re /</i>	\$ 51.70
9	Tailgate 'GL' emblem <i>X</i>	\$ 50.40
10	Tailgate inner trimboard <i>X</i>	\$ 489.00
11	Tailgate lock <i>X</i>	\$ 264.00
12	Tailgate weatherstrip <i>X</i>	\$ 391.00
13	Taillamp LH <i>X</i>	\$ 389.00
14	Taillamp corner garnish LH <i>X</i>	\$ 157.00
15	Taillamp corner garnish support LH <i>X</i>	\$ 32.80
	SUB TOTAL	\$ 5,849.20
	Less 25%	\$ 1,462.30
	SUB TOTAL	\$ 4,386.90
	SPECIAL NETT ITEM	
1	Rear bumper clips <i>re /</i>	\$ 40 50.00
2	Tailgate inner trimboard clips <i>re /</i>	\$ 40 50.00
3	Rear number plate <i>X</i>	\$ 50.00
4	Rear windscreen glass sealant <i>re /</i>	\$ 40 80.00
5	Sticker '70km/h' <i>re /</i>	\$ 15 20.00
6	Reverse sensor <i>?</i>	\$ 200? 300.00
	SUB TOTAL	\$ 570.00
	LABOUR	
	Labour to remove & refit affected portion	\$ 600 1,000.00
	Spray paint on the affected portion <i>400</i>	\$ 600 800.00
	Labour to remove & refit tailgate components	\$ 60 100.00
	Labour to remove & refit rear windscreen glass	\$ 120 200.00
	Labour to remove & refit reverse sensors	\$ 40 100.00
	To conduct wiring check	\$ X 50.00
	To apply anti rust coating	\$ 50 100.00
	SUB TOTAL	\$ 2,350.00
	GRAND TOTAL	\$ 7,306.90

5 days
4/5
10/07/23 @ 1220
Done after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	344B
Vehicle Details	
Vehicle No.:	GBL6393P
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 2.0 AUTO
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	1TR2375830
Chassis No.:	TRH2005048364
Maximum Power Output:	-
Open Market Value:	\$28,152.00
Original Registration Date:	23 Nov 2021
First Registration Date:	23 Nov 2021
Transfer Count:	0
Actual ARF Paid:	\$1,408.00
Enquire PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Enquire COE Rebate Details	
COE Expiry Date:	22 Nov 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$31,360.00
COE Rebate Amount:	\$26,229.00
Total Rebate Amount:	\$26,229.00

The information contained herein is correct as at 11 Jul 2023

OK

Toyota Hiace 2.0A DX

\$92,000 Instalment \$1,220/mth

PREMIUM AD

Shortlist Loan Calculator



Overview Financial Photo Research

Depreciation ⓘ \$10,980 / year

Reg. Date 26-Nov-2021
(8yrs 4mths 14days COE left)

Lifespan ⓘ 25-Nov-2041

Manufactured ⓘ 2021

Mileage -

Transmission Auto

Engine Cap 1,998 cc

Curb Weight ⓘ 1,680 kg

Fuel Type Petrol

COE ⓘ \$35,966

OMV ⓘ \$26,807

ARF ⓘ \$1,341

Dereg Value ⓘ \$30,142 as of today

No. of Owners ⓘ 1

Type of Veh van