



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Tang Kwai Sim	Cust No/Name LCV15740/Ms Tang Kwai Sim
103 Corporation Walk	Reg No/Reg Date SDQ3268M / 01/06/201
Singapore 618480	Date In/Mileage / 0
Contact No 97209008	Chassis No KNACC81CVH5079490
	Engine No G4LEHS212560
	Make/Model KIA/NIRO 1.6 A
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV15740	CRDVCH	30/06/2023/ 16:19		1015/ Vikneswaran Naidu A	15507		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							3840.00
RENEW RR BUMPER, RR TAILGATE							
REPAIR RR END PANEL, RR LH FENDER							
E PNT88000							100.00
REMOVE AND REFIT SENSOR							
E PNT88000							380.00
RENEW REAR WINDSCREEN							
E PNT88000							260.00
REMOVE AND REFIT TAILGATE TRIM AND MECHANICSM							
E PNT98000							2200.00
SPRAY REAR BUMPER, RR TAILGATE, RR END PANEL,							
REAR LH FENDER							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
A 10028901							100.00
CHECK WIRING AND ELECTRICAL							
M SUNDRY							4000.00
SEALING WINDSCREEN							
M SUNDRY							280.00
SUPPLY SOLAR FILM TINT							
M SUNDRY							150.00
ANTI RUST PROOFING							
M SUNDRY							80.00
SUPPLY CNC BADGE							
M SUNDRY							80.00
SUPPLY NUMBER PLATE							
M SUNDRY							50.00
SUNDRIES							
M COVER-RR BUMPER,UPR				1.00	615.00	00.00	615.00
M COVER-RR BUMPER LWR				1.00	392.00	00.00	392.00
M MOULDING ASSY-RR BUMPER SIDE,L				1.00	24.00	00.00	24.00
M REFLECTOR/REFLEX ASSY-RR LH				1.00	108.00	00.00	108.00
M COVER-RR BUMPER SIDE UNDER,LH				1.00	27.00	00.00	27.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Tang Kwai Sim	Cust No/Name LCV15740/Ms Tang Kwai Sim
103 Corporation Walk	Reg No/Reg Date SDQ3268M / 01/06/201
Singapore 618480	Date In/Mileage / 0
Contact No 97209008	Chassis No KNACC81CVH5079490
	Engine No G4LEHS212560
	Make/Model KIA/NIRO 1.6 A
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV15740	CRDVCH	30/06/2023/ 16:19		1015/ Vikneswaran Naidu A	15507
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BEAM-RR BUMPER		1.00	261.00	00.00	261.00
M BRACKET ASSY-RR BUMPER SIDE,LH		1.00	25.00	00.00	25.00
M PANEL ASSY-TAIL GATE		1.00	1478.00	00.00	1478.00
M GLASS ASSY-TAIL GATE		1.00	1179.00	00.00	1179.00
M PAD-WINDSHIELD GLASS		1.00	2.00	00.00	2.00
M EMBLEM-NIRO		1.00	25.00	00.00	25.00
M LOGO-KIA		1.00	42.00	00.00	42.00
M EMBLEM-ECO HYBRID		1.00	29.00	00.00	29.00
M LAMP ASSY-REAR COMB INSIDE,LH		1.00	636.00	00.00	636.00
M LAMP ASSY-REAR COMB OUTSIDE,LH		1.00	775.00	00.00	775.00
M LAMP ASSY-REAR COMB OUTSIDE,RH		1.00	775.00	00.00	775.00
M LAMP ASSY-REAR COMB INSIDE,RH		1.00	636.00	00.00	636.00
M BRACKET, IU ADHESIVE		1.00	26.00	00.00	26.00

Confirm & accepted by

Nett	18,855.00
8% GST on	18855.00
Total Payable	20,363.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.