

# C L APPRAISER PTE LTD

24 Penshurst Place, Singapore 556440  
Email: [clappraiser@yahoo.com](mailto:clappraiser@yahoo.com) Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## INVOICE

Shaik Imran Bn Shaik Jamal  
C/o: H L Cycle Pte Ltd  
No.1 Kaki Bukit Ave 6  
#02-58/60 AutoBay, Singapore 417883

Invoice No. : CL/210432

Ref No. : HLC/07/2103/TP

Date : 14 September 2021

DESCRIPTION	AMOUNT
<b>OUR SERVICE FEE CHARGES:</b>	
<ul style="list-style-type: none"><li>SURVEY INSPECTION FOR VEHICLE NO. <b><u>FBP 4518 P</u></b></li><li>RESURVEY INSPECTION</li><li>DIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)</li><li>TRANSPORTATION</li></ul>	
<b>GRAND TOTAL</b>	<b>S\$ 605.00</b>

E & O. E

All cheque payment should be "Crossed" and made payable to " **C L APPRAISER PTE LTD** "

We shall be grateful if you could forward our payment at your early convenience.



**CL Appraiser Pte Ltd**



24 Peshurst Place, Singapore 556440

Email: [clappraiser@yahoo.com](mailto:clappraiser@yahoo.com) Hp: 9068 8689 Fax: 6452 9783

Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Shaik Imran Bn Shaik Jamal  
C/o: H L Cycle Pte Ltd  
No.1 Kaki Bukit Ave 6  
#02-58/60 AutoBay, Singapore 417883

Date : 14 September 2021  
Our ref : HLC/07/2103/TP

Accident Date : 29 June 2021  
Inspection Date : 27 July 2021  
Repairer Name : H L Cycle Pte Ltd  
No.1 Kaki Bukit Ave 6  
#02-58/60 AutoBay, Singapore 417883

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No	: FBP 4518 P	Year / Capacity	: 2019 / 150 cc
Make / Model	: Yamaha Sniper T150	Colour	: Black
Chassis No	: MH3UG0740K0152577	Mileage	:
Engine No	: G3E6E0484252		

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front	: Pirelli	90/80 - 17	5 mm	Sport
Rear	: Pirelli	120/70 -17	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front and o/s portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: **145** copies

### REMARKS


This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$4,800.00** on a contractual basis.

Under normal circumstances, the repair period would be about 20 (Twenty) working days.



# SCL APPRAISER PTE LTD

Vehicle Registration No.: FBP 4518 P

Our Ref No.: HLC/07/2103/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

## SPARE PARTS - LIST ITEMS

2	Front fork tube assy	Damage	\$ 640.00	\$ 640.00
1	Front wheel rim	Damage	\$ 480.00	\$ 480.00
1	Fork under bracket	Damage	\$ 185.00	\$ 185.00
1	Front rim shaft	Necessary	\$ 45.00	\$ 45.00
1	Front rim bearing	Necessary	\$ 38.00	\$ 38.00
1	Front brake disc	Damage	\$ 155.00	\$ 155.00
1	Handle-bar	Damage	\$ 88.00	\$ 88.00
2	Handle-bar ends	Damage	\$ 64.00	\$ 64.00
1	Hand grip ( 1 set )	Necessary	\$ 55.00	\$ 55.00
1	Handle-bar inner bracket	Damage	\$ 68.00	\$ 68.00
2	Side mirrors	Damage	\$ 110.00	\$ 110.00
1	Clutch lever	Damage	\$ 30.00	\$ 30.00
1	Brake lever	Damage	\$ 32.00	\$ 32.00
1	Brake master pump	Damage	\$ 135.00	\$ 135.00
2	Front signals	Damage	\$ 190.00	\$ 190.00
1	Headlamp	Damage	\$ 185.00	\$ 185.00
1	Fairing assy (1 set )	Damage	\$ 758.00	\$ 758.00
2	Side cowling lamps	Damage	\$ 180.00	\$ 180.00
1	Radiator	Damage	\$ 458.00	\$ 458.00
1	Front footrest bracket	Damage	\$ 65.00	\$ 65.00
1	Front o/s footrest rubber	Necessary	\$ 35.00	\$ 35.00
1	Brake pedal	Damage	\$ 42.00	\$ 42.00
1	Rear o/s footrest	Damage	\$ 40.00	\$ 40.00
1	Rear o/s footrest bracket	Intact	\$ 78.00	
1	Exhaust assy	Damage	\$ 485.00	\$ 485.00
1	Exhaust protector	Damage	\$ 60.00	\$ 60.00
1	Exhaust end cap	Damage	\$ 45.00	\$ 45.00
1	Basket	Damage	\$ 50.00	\$ 50.00
			<b>\$ 4,796.00</b>	<b>\$ 4,718.00</b>
			<i>Less 10%</i>	<i>\$ 471.80</i>
<b>Total Cost - List Items</b>			<b>\$ 4,316.40</b>	<b>\$ 4,246.20</b>

Vehicle Registration No.: FBP 4518 P

Our Ref No.: HLC/07/2103/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
<b>List Items Total c/f</b>			<b>\$ 4,316.40</b>	<b>\$ 4,246.20</b>

**SPECIAL NETT ITEMS**

1	Number plate (1 set)	Damage	\$ 28.00	\$ 28.00
2	Fork oils	Necessary	\$ 30.00	\$ 30.00
2	Fork oil seals	Necessary	\$ 56.00	\$ 56.00
1	Steering cone (1 set)	Necessary	\$ 90.00	\$ 90.00
1	Rear box	Damage	\$ 280.00	\$ 280.00
1	Rear box bracket with tray	Damage	\$ 150.00	\$ 150.00
1	Front tyre (Depreciation)	Damage	\$ 200.00	\$ 100.00
1	Coolant	Necessary	\$ 25.00	\$ 25.00
1	Sticker (1 set)	Necessary	\$ 95.00	\$ 95.00
<b>Total Cost - Special Nett items</b>			<b>\$ 954.00</b>	<b>\$ 854.00</b>

**Total cost of parts**

<b>\$ 5,270.40</b>	<b>\$ 5,100.20</b>
--------------------	--------------------



## C L APPRAISER PTE LTD

Vehicle Registration No.: FBP 4518 P

Our Ref No.: HLC/07/2103/TP

S/No	Description	Repairer's Estimate	Revised Amount
------	-------------	---------------------	----------------

Total cost of parts c/f

\$ 5,270.40 \$ 5,100.20

### LABOUR

1	To provide towing service.	\$ 50.00	\$ 50.00
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 50.00
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 480.00	\$ 400.00
4	To check , repair and straighten body frame to the original position.	\$ 350.00	\$ 350.00

GRAND TOTAL

\$ 6,230.40 \$ 5,950.20

Vehicle Registration No.: FBP 4518 P

Our Ref No.: HLC/07/2103/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 4,800.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

**Disclaimer**

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

C L APPRAISER PTE LTD



Cheong K. H  
Automotive Appraiser