



Inspection Services Pte Ltd

Date : 29 August 2022

To : **NTUC Income Insurance Co-operative Limited**
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556

Attn : Ms Jasmine Tan

AJAX Inspection Services Pte Ltd

120 Lower Delta Road

#08-08, Cendex Centre

Singapore 169208

Tel: +65 6255 0808

Fax: +65 6849 9155

info@ajaxinspection.com

Invoice No – AV33143

Company Reg No -201318067R

GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER : MT/1136403-002
OUR REF : AVS2021-28100/ID
TP VEHICLE NO : FBP4518P
CLAIM TYPE : PRE-REPAIR SURVEY
DATE OF SURVEY : 28 July 2021

No.	Description	Amount (S\$)
1	Professional fee	100.00

Subtotal 100.00
GST 7.00% 7.00
Total 107.00

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd

Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Jasmine Tan

Assign Date:	27/07/2021	Survey Date:	28/07/2021	Adjustment Date:	25/08/2022
Accident Date:	29/06/2021	TP Policy No:	5108757094-02	Our Ref:	AVS2021-28100/ID
Place of Survey:	H L Cycle Pte Ltd 1 Kaki Bukit Avenue 6 #02-58 Autobay Singapore 417883			Your Ref:	MT/1136403-002
				Claim Type:	Third Party
				Claimant:	Shaik Imran Bin Shaik Jamal

Description of Vehicle:

Veh. No:	FBP4518P	Make/Model:	Yamaha Sniper T150	Sum Insured (\$\$):	Market Value
Colour:	Black	Engine No:	G3E6E0484252	Mkt Value (\$\$):	\$9,000.00
Engine Capacity:	150 cc	Chassis No:	MH3G0740K0152577	Excess (\$\$):	NA
Odometer:	42858	Reg. Date:	08/04/2019		

Condition of Vehicle:

General:	Fair	Modification:	No	Steering:	Affected
Handbrake:	Affected	Footbrake:	Affected	Paint work:	Fair
Tyre Make:	Pirelli				
Front Tyre Size:	90/80R17	Front Side:	4mm		
Rear Tyre Size:	90/80R17	Rear Side:	4mm		

Description of Damage:

The vehicle sustained damage on the front and right portions.

Remarks:

Our recommended amount for the cost of contract lumpsum repair is S\$3,400.00 with approximately three (3) working days to complete. However, no finalisation was agreed with the repairer.

**COMPLETED 24 AUG 2022**

Adjuster: Billy Loh
Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:			FBP4518P	Our Ref: AVS2021-28100/ID	
No.	Qty	Description of Parts	Condition	Third Party Survey Report S\$	Our Recommendation S\$
List Items					
1	2	Front fork tube assy	Bent	640.00	640.00
2	1	Front wheel rim	Repair	480.00	--
3	1	Fork under bracket	Bent	185.00	185.00
4	1	Front rim shaft	Not necessary	45.00	--
5	1	Front rim bearing	Not necessary	38.00	--
6	1	Front brake disc	Not necessary	155.00	--
7	1	Handle bar	Bent	88.00	88.00
8	2	Handle bar ends	Dented	64.00	64.00
9	1 set	Hand grip	Cut	55.00	55.00
10	1	Handle bar inner bracket	Bent	68.00	68.00
11	2	Side mirrors	Cut	110.00	110.00
12	1	Clutch lever	Dented	30.00	30.00
13	1	Brake lever	Dented	32.00	32.00
14	1	Brake master pump	Not necessary	135.00	--
15	2	Front signals	Cut	190.00	190.00
16	1	Headlamp	Cut	185.00	185.00
17	1 set	Fairing assy	Cracked	758.00	758.00
18	2	Side cowling lamps	Cracked	180.00	180.00
19	1	Radiator	Dented	458.00	458.00
20	1	Front footrest bracket	Dented	65.00	65.00
21	1	Front o/s footrest rubber	Dented	35.00	35.00
22	1	Brake pedal	Dented	42.00	42.00
23	1	Rear o/s footrest	Dented	40.00	40.00
24	1	Rear o/s footrest bracket	Not necessary	--	--
25	1	Exhaust assy	Dented	485.00	485.00
26	1	Exhaust protector	Dented	60.00	60.00
27	1	Exhaust end cap	Dented	45.00	45.00
28	1	Basket	Bent	50.00	50.00
Sub Total:				4,718.00	3,865.00
Discount (less 10%):				471.80	386.50
				4,246.20	3,478.50

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R



Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:				Our Ref: AVS2021-28100/ID	
No.	Qty	Description of Parts	Condition	Third Party Survey Report S\$	Our Recommendation S\$
Special Nett Items					
1	1 set	Number plate	Necessary	28.00	15.00
2	2	Fork oils	Necessary	30.00	30.00
3	2	Fork oil seals	Necessary	56.00	40.00
4	1 set	Steering cone	Necessary	90.00	40.00
5	1	Rear box	Cut	280.00	200.00
6	1	Rear box bracket with tray	Not necessary	150.00	--
7	1	Front tyre (Depreciation)	Not necessary	100.00	--
8	1	Coolant	Necessary	25.00	25.00
9	1 set	Sticker	Necessary	95.00	45.00
Sub Total:				854.00	395.00
Total Parts Price:				5,100.20	3,873.50

Labour Cost			
1	To provide towing service.	50.00	--
2	To check electrical system, wire harness and focus headlamp.	50.00	20.00
3	To provide labour charges, workmanship to dismantle above damaged parts; re-align body structure and damaged consistent to the accident.	400.00	250.00
4	To check, repair and straighten body frame to the original position.	350.00	150.00
Sub Total:		850.00	420.00
Grand Total:		5,950.20	4,293.50

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R