



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDN 1111K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	2,114.00	-
1	REAR DOOR	BENT/WARPED	2,349.00	2,349.00
1	ROCKER GARNISH	SERVICEABLE	680.00	-
1	WHEEL RIM	DENTED	850.00	850.00
1	FRONT DOOR	TO REPAIR SEE LABOUR	2,450.00	-
1	FRONT DOOR RUBBER	SERVICEABLE	387.00	-
	LESS 10% DISCOUNT		-	-319.90
			8,830.00	2,879.10
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR RUBBER (\$288.00) (50%) (SN)	NECESSARY	367.00	144.00
1	TYRE (60%) (SN)	CUT	350.00	210.00
			717.00	354.00
	<u>LABOUR</u>			
	RUST PROOFING.		100.00	30.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND FRONT DOOR.		1,200.00	600.00
	SPRAY PAINTING.		1,200.00	1,080.00
			2,500.00	1,710.00
	GRAND TOTAL		12,047.00	4,943.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CS/AGI23006758/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.