

ASS. REC. BY:

REF:

AG1 / 23006758/Kny3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDN 1111K

Yr Regn:

09, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mr CIA 180 c.c

1595

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

5009

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD1173422N 242120

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

S

mm

R/Bal.

7

mm

L/Bal.

S

mm

L/Bal.

7

mm

D.O.A.

5/7/23

D.O.I.

5/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 GIA not ready

11/7 L1 Rm @ 4000/- Cabin (Red. \$ 8047, 66%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



方 商 昭 噴 漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Chng Lee Huang
Apt Blk306 Shunfu Road
#04-117
Singapore 570306

Dear sir
Estimate cost of repair to vehicle no. SDN1111K
To supply

1. Rear bumper	2,114.00	X
2. Rear door	2,349.00	✓
3. Rear door rubber 288	367.00	508m 1443m
4. Rocker garish	680.00	X
5. Wheel rim	850.00	✓
6. Tyre	350.00	608m 2105m
7. Front door	2,450.00	X
8. Front door rubber 108	387.00	X
Labour charge	100.00	301
Rust proofing	1,200.00	6001
Panel beating	1,200.00	10801
Spray painting		
Total	12,047.00	

Not Not home
11pm 8400dp
Merry After Paint
4 days

Your faithfully

ALBERT POON

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: