

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT HSBC LIFE (SINGAPORE) PTE LTD CS3/HSB23006787/Knp3m4 Ref: 10 MARINA BOULEVARD #48-01 MARINA BAY Date: 19/07/2023 FINANCIAL CENTRE TOWER 2 SINGAPORE ATTN: TEO KITTY Code: HSB Policy Particulars :- (THIRD PARTY CLAIM) 1. SHD 7165X SMZ 7782P Insured Veh. Veh. Inspected VFX/P2419138 0.00 Policy No. Coverage (\$) S3M04NQ3 0.00 Claim No. Excess (\$) TEO KITTY 05/07/2023 **Assign From Assign Date** 2. **Vehicle Particulars & Condition** MERCEDES E200 (A) 1991 Make & Model c.c **HIDDEN** 2014 Engine No. Year of Reg. WDD2120342B033128 METALLIC SILVER Chassis No. Colour Odometer 111018 KM **IN ORDER** Steering **IN ORDER** STANDARD ALLOY RIM Modification **Brakes** GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 245/40 R18 **GOODYEAR** 7 mm L/H Front Tyre 245/40 R18 GOODYEAR 7 mm 7 mm GOODYEAR R/H Rear Tyre 245/40 R18 L/H Rear Tyre 245/40 R18 **GOODYEAR** 7 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. 5. **General Information** 26/06/2023 **Inspect Date / Time** 05/07/2023 (01:30 PM) **Accident Date** WAH YU AUTOMOTIVE BODY WORK Survey held at 176 SIN MING DRIVE #05-09 SINGAPORE 575721 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500

Report Ref No. CS3/HSB23006787/Knp3m4

Estimate Days of Repair

Inspected By

5b.

KONG SENG CHEONG

Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

4 Working Days