

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123006796/UVP3Q2**Date:** 27/07/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : YQ9798L**Insured Vehicle No :** XD8524Y

Date of Loss: 23/06/2023

Nature of Claim: TP

Claim No: CDMFG23001538

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **YQ9798L**

Make & Model: ISUZU NPR85UH5A, 3.0 D (M)

Engine No: 4JJ14G0759

Reg. Date: 27/03/2020 (Man. Year: 2019)

Chassis No: JAANPR85HK7100896

Colour: White

Odometer: 125279 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/85 R16

Rear Tyre Size: 205/85 R16 (D)

Front Left Side: Maxxis 6 mm

Rear Left Side: Maxxis 6/6 mm

Front Right Side: Maxxis 6 mm

Rear Right Side: Maxxis 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,430.50	14,654.56	15,775.94	51.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,550.00	2,630.00	4,920.00	65.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,980.50	17,284.56	20,695.94	54.49
Approved Total (Overridden) (S\$)		13,800.00		
Nett Amount (S\$)	37,980.50	13,800.00	24,180.50	63.67

INSPECTION

Date of Assignment: 05/07/2023

Date Inspected: 05/07/2023 Inspected At:

Liu's Brother Auto Workshop (HQ)

1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Jul 2023)	
Parts:	N/A	ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ9798L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,470.00 F	*1,175.00 FL
2	1		*SET FRONT BUMPER CLIPS	Not Necessary	65.00 FS	*- FS
3	2		*FRONT BUMPER BRACKET	Not Necessary	546.00 F	*- FL
4	1		*FRONT NUMBER PLATE & BASE	Bent	48.00 FS	*40.00 FS
5	1		*FRONT GRILLE CHROME	Cracked	620.60 F	*620.60 FL
6	2		*FRONT HEAD LAMP	Cracked	1,160.00 F	*960.00 FL
7	2		*FRONT SIGNAL LAMP	Cracked	470.00 F	*470.00 FL
8	1		*FRONT CORNER PANEL	N/S Repair / O/S Cracked	1,372.00 F	*466.00 FL
9	1		*FRONT PANEL	Dented / Warped	1,332.50 F	*1,215.00 FL
10	1		*FRONT ISUZU EMBLEM	Necessary	214.30 F	*118.00 FL
11	1		*FRONT REWARD -NP EMBLEM	Not Necessary	176.20 F	*- FL
12	1		*FRONT LH MIRROR ARM	Not Necessary	346.00 F	*- FL
13	1		*FRONT LH SIDE MIRROR ROUND	Not Necessary	137.00 F	*- FL
14	1		*FRONT LH WINDSCREEN GLASS WEATHERSTRIP REAR	Not Necessary	234.90 F	*- FL
15	1		*FRONT LH VACUUM PUMP PANEL	Not Necessary	2,971.00 F	*- FL
16	1		*FRONT LH VACUUM PUMP HOSE	Not Necessary	315.00 F	*- FL
17	1		*FRONT LH TURBO HOSE TOP	Not Necessary	670.00 F	*- FL
18	1		*FRONT LH TURBO HOSE LOWER	Not Necessary	410.00 F	*- FL
19	1		*FRONT LH AIR CLEANER ASSY	Cracked	1,950.00 F	*1,020.00 FL
20	1		*FRONT LH AIR CLEANER HOSE	Not Necessary	370.00 F	*- FL
21	1		*FRONT LH AIR DUCT	Twisted	660.00 F	*305.00 FL
22	2		*REAR CARGO BOX BACK DOOR	Dented / Bent	3,900.00 FS	*2,400.00 FS
23	2		*REAR TAILGATE HINGES 2 SETS TOP & BOTTOM	Serviceable	500.00 FS	*- FS
24	2		*REAR T-HOOK	Repair	300.00 FS	*- FS
25	2		*REAR LOCK BAR	Repair	800.00 FS	*- FS
26	2		*REAR TAIL LAMP	Cracked	484.00 F	*484.00 FL
27	1		*REAR STEP WOODEN PLANK	Cracked	280.00 FS	*280.00 FS
28	2		*REAR LONG BEAM (CHASSIS TOP)	Cracked	2,900.00 FS	*2,600.00 FS
29	1		*REAR FLOOR LOWER WOODEN PLANK	Cracked	380.00 FS	*380.00 FS
30	1		*REAR SAFETY BAR	Bent	600.00 FS	*600.00 FS
31	2		*REAR SAFETY BAR BRACKET	Bent	700.00 FS	*400.00 FS
32	2		*REAR WHEEL FENDER	Torn	900.00 F	*760.00 FL
33	2		*REAR SIDE GUARD BRACKET	Bent	500.00 FS	*500.00 FS
34	6		*REAR U BRACKET	Repair	1,200.00 F	*- FL
35	1		*REAR CARGO BOX PANEL FRONT	Dented / Bent	1,400.00 FS	*1,000.00 FS
36	1		*REAR NUMBER PLATE & BASE	Not Necessary	48.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 30,430.50 15,793.60
- List Item Discount on L Items 0.00/15.00% (\$\$) 0.00 1,139.04

Total Parts (\$\$) 30,430.50 14,654.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CORPORATE ADVERTISEMENT & ARTWORK	New	1,800.00	0.00
2	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER TEST	New	150.00	0.00
3	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	120.00	30.00
4	TO REMOVE,REPLACE AND TRANSFER CARGO BOX ,FITTING AND MECHANISMS REPAIR CHASSIS	New	600.00	400.00
5	REPAIRING OF REAR CARGO BOX LABOR CHARGE	New	2,500.00	300.00
6	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	1,000.00
7	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	900.00	850.00
8	TO APPLY RUST PROOFING RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	280.00	50.00
Gross Labour Cost (S\$)			7,550.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >