

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI23006816/UNP3Q2**Date:** 14/07/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : GBF3401B **Insured Vehicle No :** YP5828R

Date of Loss: 26/06/2023 Nature of Claim: TP Claim No: CDMCG23001579

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF3401B**

Make & Model: TOYOTA HIACE, 2.0 (A) Engine No: 1KD2600752

Reg. Date: 16/09/2016 (Man. Year: 2016) Chassis No: KDH2010193091

Colour: Red Odometer: 187792 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15

Front Left Side: Austone 6 mm Rear Left Side: Austone 6 mm

Front Right Side: Austone 6 mm Rear Right Side: Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	447.00	120.00	327.00	73.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	430.00	300.00	130.00	30.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	877.00	420.00	457.00	52.11

INSPECTION

Date of Assignment: 05/07/2023

Date Inspected: 05/07/2023 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @
KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2023)
Parts:	213	TOYOTA HIACE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF3401B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE TOYOTA LOGO MOTIF	Serviceable	167.00 F	*- F
2	1		*REAR TAILGATE 70KM/H	Necessary	15.00 FS	*10.00 FS
3	1		*REAR TAILGATE 8 PAX STICKER	Necessary	15.00 FS	*10.00 FS
4	1		*REAR CORPORATE ADVERTISEMENT & ARTWORK	Necessary	250.00 FS	*100.00 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	447.00 120.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR FOR PANEL BEATING CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	200.00	100.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	200.00	200.00
3	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	30.00	0.00
Gross Labour Cost (\$\$)			430.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >