

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	HSBC LIFE (SINGAPORE) PTE LTD		Ref:	CS3/HSB23006860/Unp3m4	
		EVARD #48-01 MARINA BAY RE TOWER 2 SINGAPORE	Date:	17/07/2023	
	ATTN: KHOR SAW	THENG	Code:	HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 3036S	Veh. Inspected	SJV 4941Z	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S3M04NV8	Excess (\$)	0.00	
	Assign From	KHOR SAW THENG	Assign Date	06/07/2023	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AVANTE (A)	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	KMHDU41BMAU962843	Colour	SILVER	
	Odometer	203029 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65R15	MICHELIN	6 mm	
	L/H Front Tyre	195/65R15	MICHELIN	6 mm	
	R/H Rear Tyre	195/65R15	MICHELIN	6 mm	
	L/H Rear Tyre	195/65R15	MICHELIN	6 mm	
4. Description of Damages					
	THE VEHICLE SUS	IE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5.	5. General Information				
	Accident Date	05/07/2023	Inspect Date / Time	06/07/2023 (02:45 PM)	
	Survey held at	NO. 2, KAKI BUKIT AVENUE 2 #	01-33, S 417921		
	Repairer WILLIAM LEE CAR AIR CON ENGINEERING				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
	5b. Estimate Days of Repair				
5b.		Estimate	Days of Repair		

Report Ref No. CS3/HSB23006860/Unp3m4

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser