

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 7615M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER ASSY	GRAZED/WARPED	1,668.80	823.00
1	FRONT BUMPER RIGHT FOG LAMP	NOT NECESSARY	448.50	-
1	FRONT BUMPER RIGHT SIDE RETAINER	BENT/NECESSARY	54.20	54.20
1	FRONT BUMPER REINFORCEMENT	DENTED	521.30	392.00
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	161.40	-
1	FRONT RIGHT FENDER	DENTED	1,182.30	812.00
1	FRONT RIGHT HEADLAMP ASSY	CRACKED	2,688.70	1,580.00
	LESS 25% DISCOUNT		-1,681.30	-915.30
			5,043.90	2,745.90
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE WITH GARNISH (SN)	NOT NECESSARY	100.00	-
10	FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	FRONT BUMPER LOWER SPOILER ASSY (SN)	GRAZED/WARPED	1,500.00	300.00
1	FRONT BUMPER LOWER SPOILER SEALANT (SN)	NECESSARY	100.00	30.00
10	FRONT BUMPER LOWER SPOILER CLIPS (SN)	NECESSARY	60.00	20.00
			1,820.00	380.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN ACCIDENT AFFECTED AREA AND REPLACE ACCIDENT DAMAGED PARTS.		1,200.00	500.00
	TO PUTTY AND SPRAY PAINTING ACCIDENT PORTION.		1,200.00	800.00
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		80.00	30.00
	TOWING SERVICES.		120.00	80.00
	TO APPLY ANTI RUST PROOFING TO ACCIDENT AFFECTED AREA.		140.00	30.00
			2,740.00	1,440.00
	GRAND TOTAL		9,603.90	4,565.90



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,650.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/EGI23004451/Dqy3m4-1



Automotive Assessor / Investigator