

## VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 65/TP/2023

Date: 22/5/2023

### REFERENCE

Date of loss: 1/5/2023  
 Claimant: Lin Lichong

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN7615M	Make &	Toyota
Reg date:	26/2/2009	Model	Camry2.4G A
Colour:	Blue	Engine No:	2AZC419529
Type:	Motor Car	Chassis No:	ACV403166068
Type of Claims:	Third Party	Odometer No:	133022km
		Engine Cap:	2362cc

### CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition:	Good	Steering:	Good	Engine Modification	Nil
Paint work:	Good	Handbrake:	Good	Pre-accident	
		Footbrake:	Good	Damage:	Nil

### CONDITION OF TYRES

Front Left Size:	Kumho 225/50R18 70%	Front Right Size:	Kumho 225/50R18 70%
Rear Left Size:	Kumho 225/50R18 70%	Rear Right Size:	Kumho 225/50R18 70%

*The above percentages represent the remaining life of the tyre threads*

### COST OF REPAIRS

	Repairer S\$	Adjuster S\$
Parts	\$ 6,863.90	\$ 6,503.90
Labour	\$ 2,740.00	\$ 2,280.00
Calculated Cost (S\$) :	<u>\$ 9,603.90</u>	<u>\$ 8,783.90</u>


**Recommended Lump Sum Repair Cost (S\$) : \$ 7,000.00**

Date of Assignment: 9/5/2023  
 Date Inspected: 9/5/2023  
 Est. repair Period: 07 days

Inspected At: Arc Motorworks Pte Ltd  
 10 Kaki Bukit Road 2  
 #01-21 First East Center  
 Singapore 417868

### POINT OF IMPACT

Damaged at the right hand front portion.



### BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's Vehicle at 24 New Industrial Road.

### GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the right hand front portion.

### SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$9,603.90. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$7,000.00.

We have not authorised the repair. Under normal circumstances, estimated **07** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



**Dave Chang**  
Automotive Appraiser  
AUTO. ENG, CAE, CGI  
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

*Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.*

## ANNEX A

**REPAIR DETAILS**

## Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount	
1	1	Front bumper assy	grazed/warped	\$ 1,668.80	\$ 1,668.80	823 ✓
2	1	Front bumper right fog lamp	bent	\$ 448.50	\$ 448.50	X nn
3	1	Front bumper right side retainer	bent/necessary	\$ 54.20	\$ 54.20	✓
4	1	Front bumper reinforcement	dented	\$ 521.30	\$ 521.30	392 ✓
5	1	Front bumper inner sponge	warped	\$ 161.40	\$ 161.40	X nn
6	1	Front right fender	dented	\$ 1,182.30	\$ 1,182.30	812 ✓
7	1	Front right headlamp assy	cracked	\$ 2,688.70	\$ 2,688.70	1580 ✓
				<u>\$ 6,725.20</u>	<u>\$ 6,725.20</u>	3661.20
		Less 25%		\$ 1,681.30	\$ 1,681.30	-20%
				<u>\$ 5,043.90</u>	<u>\$ 5,043.90</u>	2745.90
<u>Special Nett Items</u>						
1	1	Front no plate with garnish	necessary	\$ 100.00	\$ 80.00	X nn
2	10	Front bumper clips	necessary	\$ 60.00	\$ 50.00	30
3	1	Front bumper lower spoiler assy	grazed/warped	\$ 1,500.00	\$ 1,200.00	300
4	1	Front bumper lower spoiler sealant	necessary	\$ 100.00	\$ 80.00	30
5	10	Front bumper lower spoiler clips	necessary	\$ 60.00	\$ 50.00	20
				<u>\$ 1,820.00</u>	<u>\$ 1,460.00</u>	380
<b>Total parts</b>				<b>\$ 6,863.90</b>	<b>\$ 6,503.90</b>	

## ANNEX B

### REPAIR DETAILS

#### Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount	
1	Labour for panel beating, cut, weld, straighten accident affected area and replace accident damaged parts.	\$ 1,200.00	\$ 1,000.00	500
2	To putty and spray painting accident portion.	\$ 1,200.00	\$ 1,000.00	800
3	To check wiring and focus front headlamp.	\$ 80.00	\$ 60.00	30
4	Towing services.	\$ 120.00	\$ 100.00	80
5	To apply anti rust proofing to accident affected area.	\$ 140.00	\$ 120.00	30
<b>Total labour :</b>		<b>\$ 2,740.00</b>	<b>\$ 2,280.00</b>	<b>1440</b>

## ANNEX C

### REPAIR DETAILS

#### Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
<b>Total parts :</b>	<b>\$ 6,863.90</b>	<b>\$ 6,503.90</b>
<b>Total labour :</b>	<b>\$ 2,740.00</b>	<b>\$ 2,280.00</b>
<b>Total repair cost :</b>	<b>\$ 9,603.90</b>	<b>\$ 8,783.90</b>

**Adjusted Repair Cost (Lump Sum Repair)**

**\$ 7,000.00**

4565.90

4 days

L/S - 3652.72  
= 3650