

VICOM LTD 385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555 Facsimile (65) 6458 1040

www.vicom.com.sg Company Registration No: 198100320K

TAX INVOICE

SBS Transit Ltd 205 BRADDELL ROAD SINGAPORE 579701

ATTN: MOTOR CLAIMS DEPT.

SBS3290K

GST REG No.

: M9-0000652-A

CUSTOMER ID : VACS0001

INVOICE No.

: CL026483

INVOICE DATE: 06/07/2023

CLAIM No.

VEHICLE No.

ACCIDENT DATE :

AR-2023-3079

01/06/2023

PAYMENT TERM: 30 Days Credit

DESCRIPTION	QTY	UNIT PRICE(SG	\$) AM	MOUNT (SG\$)
Photographs	84	1.00	\$	84.00
Transportation	1	60.00	\$	60.00
VAC Assessment Fee	1	280.00	\$	280.00

BANK ACCOUNT NAME : VICOM LTD

: DBS Bank Ltd(DBS)

BANK ACCOUNT NO.

: 015-002201-9

GROSS AMOUNT

424.00

BANK BRANCH

BANK

: Thomson Branch

GST @ 8%

33.92

\$


\$

BANK / BRANCH CODE: 7171 / 015

INVOICE AMOUNT

457.92

This is a computer generated TAX INVOICE No signature required





VICOM LTD 385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555 Facsimile (65) 6458 1040

www.vicom.com.sg Company Registration No: 198100320K

SURVEY REPORT

GENERAL INFORMATION

VAC Ref. No. : 572389 Claim No. : AR-2023-3079
Accident Date : 01/06/2023 Claim Type : THIRD PARTY
Assignment Date : 08/06/2023 Policy No. :

Survey Date : 09/06/2023 Survey Report Date : 06/07/2023

VEHICLE PARTICULARS

Vehicle No. : SBS3290K Chassis No. : YV3S4P922DA161008

Finalised Dt.:

Registration Date : 27/05/2013 Engine No. : D9190177

Make : VOLVO Engine Cap. : 9364 CC

Model : B9TL Transmission: AUTOMATIC

Colour : WHITE / PURPLE

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake : SERVICEABLE Steering : SERVICEABLE

Hand Brake : SERVICEABLE Modification: NONE

Mileage : 530612.8

TYRES	SIZE	<u>MAKE</u>	BALANCE(mm)
FRONT RH	275/70R22.5	BRIDGESTONE	7
FRONT LH	275/70R22.5	BRIDGESTONE	7
REAR RH	275/70R22.5	BRIDGESTONE	7
REAR LH	275/70R22.5	BRIDGESTONE	7

SURVEY CONDUCTED AT

1470 BEDOK NORTH AVE 4

SINGAPORE 489946.TEL:62444518

REMARKS

[1]Workshop Estimate : S\$ 4,695.82 [2]Our Adjustment : S\$ 4,507.82

[3]Repair Period : 3 days

[4] We have not authorised repairs. This survey was carried out on without

prejudice basis.

2927.82

VICOM LTD SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition		Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Side Sheetmetal Panel	Deformed/Grazed		1041.87	1041.87
2	1	Side Sheetmetal Panel	Grazed		266.41	266.41
_	•					
3	8	M8x16 Allen Head Bolt Patched	Necessary -		66.64	66.64
4	1	Bumper Corner Cl2 Frt Bumper F/G N/S	Torn		342.69	342.69
5	1	Single View Mirror O/S Electric	Missing		181.14	181.14
6	1	Stkr Adblue Wright Dd	Necessary		0.21	0.21
7	1	Stkr Pls Fold Stroller If Crowded	Necessary		1.96	1.96
8	1	Stkr Emerg Ctl Green Horizontal	Necessary		0.40	0.40
9	1	Stkr Sbs Transit Os/Ns Sg Bus	Necessary		8.00	8.00
10	1	Handle Exit Door No.3 & 4	Deformed		14.56	14.56
11	1	Side Sheetmetal Panel	Deformed		1003.94	1003.94
			Subtotal	:	2927.82	2927.82
			TOTAL	:	2927.82	2927.82
		TOTAL FOR SPARE PARTS		:	2927.82	2927.82

VICOM LTD SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Description			Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Workshop labour			188.00	0.00
2	Contractor's repair charges			1580.00	1580.00
		TOTAL FOR LABOUR AND SPRAY PAINTING	:	1768.00	1580.00

Summary

Description		Workshop Estimate (S\$)	VAC Adjstment (S\$)
TOTAL FOR SPARE PARTS	:	2927.82	2927.82
TOTAL FOR LABOUR AND SPRAY PAINTING	:	1768.00	1580.00
TOTAL REPAIR COST	:	4695.82	4507.82

VICOM LTD SURVEY REPORT

Annex C: Conclusion

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained front, right and left portion damage.

The damages seen during our survey were view mirror rh, front bumper lh, front wheel arch lh, exit door bottom handle lh, battery cover rh, and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

We examined all the front, right and left portion damages and assessed they were from a collision or impact nature.

By cross-referencing with the e-filed report, we were satisfied the damages were consistent with the circumstances of accident as detailed.

ASSESSOR'S RECOMMENDATION

Sbs Transit Ltd - (Bedok Bus Depot) estimated a repair cost of S\$4,695.82. We adjusted it to S\$4,507.82 on a part-by-part basis.

Accordingly, we recommend repairs to this vehicle be carried out on a part-by-part basis at \$\$4,507.82.

The repairs would require a period of 3 working days.

We submit our survey report for your kind attention and would add the survey was carried out to the best of our ability, knowledge and experience.

REMARKS

SBS Transit, as owner of a large fleet and having an infrastructure of own workshops to maintain its buses at various depots, would have the parts price at costs. The parts are in the inventory. Correspondingly, the labour charge is actual cost based on man hours expended for the repairs. SBS Transit provides transportation to the general public. The repairs carried out by SBS Transit workshops is not a profit entity.

Favacho Patrick Gerard for VICOM Ltd

This report is confidential and is used for the purpose of servicing our clients and their agents. We will not be responsible for the disclosure of such information or any of its part thereof by any non-contracting party. All rights reserved.







VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023








VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023



VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023







VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023




VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023



VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023



VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023








VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023



VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023







VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023




VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023








VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023








VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023




VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023



VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023



VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023







VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023



VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023











VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023







VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023







VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023







VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023









VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023







VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023







VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023







VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023







VICOM ASSESSMENT CENTRE VEHICLE No.: SBS3290K ACCIDENT DATE: 01/06/2023