7/27/23, 4:54 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI23006896/KNY3Q2

27/07/2023 Date:

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle SNL9292K Insured Vehicle No: SNC5454J No:

Date of Loss: 02/07/2023 Nature of Claim: TP Claim No: CDMPG23001626

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNL9292K

Make & Model: TOYOTA COROLLA, 1.6 (A) 1ZRX533103 Engine No:

Reg. Date: 06/10/2015 (Man. Year: 2015) Chassis No: MR053REH104539464

Colour: Metallic Grey Odometer: 117593 km

Engine Capacity: 1598 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Nο Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 205/55 R16 Rear Tyre Size: Front Left Side: Kumho 9 mm Rear Left Side: Yokohama 8 mm Front Right Side: Kumho 9 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,495.00	1,578.27	3,916.73	71.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,060.00	1,290.00	54.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,845.00	2,638.27	5,206.73	66.37
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	7,845.00	2,100.00	5,745.00	73.23
+ GST 8.00/8.00% (S\$)	627.60	168.00	459.60	73.23
Nett Amount (S\$)	8,472.60	2,268.00	6,204.60	73.23

INSPECTION

Date of Assignment: 07/07/2023

> 60 JALAN LAM HUAT #05-21 CARROS CENTRE

Date Inspected: 07/07/2023 Inspected At: SINGAPORE 737869

Repairer: My Car Consultant Pte Ltd (Jalan Lam

Huat) (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: **HUEY YON**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/27/23, 4:54 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Jul 2023)

Parts: 143 TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNL9292K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty F	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID WEATHERSTRIP	Serviceable	212.00 FL	*- FL
2	1		*TAILAMP RH	Serviceable	612.00 FL	*- FL
3	1		*REAR BUMPER	Buckled / Bent	798.00 FL	*515.70 FL
4	1		*REAR BUMPER SIDE RETAINER RH	Distorted	112.00 FL	*112.00 FL
5	1		*REAR BUMPER BRACKET RH	Bent	168.00 FL	*168.00 FL
6	2		*REAR BUMPER SENSOR	Serviceable	762.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	395.00 FL	*395.00 FL
8	1		*REAR BUMPER REFLECTOR RH	Cracked	112.00 FL	*112.00 FL
9	1		*REAR BUMPER UNDERCOVER	Serviceable	315.00 FL	*- FL
10	1		*REAR FENDER RH	Repair	698.00 FL	*- FL
11	2		*REAR FENDER COWLING	Serviceable	716.00 FL	*- FL
12	1		*REAR END PANEL	Bent	695.00 FL	*695.00 FL
13	1		*END PANEL TOP GARNISH	Serviceable	278.00 FL	*- FL
14	1		*REAR FLOOR PANEL SIDE RH	Serviceable	312.00 FL	*- FL
15	1		*REAR SPARE TYRE TOP BOARD	Serviceable	357.00 FL	*- FL
16	1		*REAR EXHAUST PIPE HEAT SHIELD	Serviceable	398.00 FL	*- FL
17	1		*SET TAILAMP CLIPS	Not Necessary	40.00 FS	*- FS
18	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
19	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
20	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*30.00 FS
21	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
F=Fra	nchise pa	art. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	7,230.00	2,077.70
	- List Item Discount on L Items 25.00/25.00% (S\$)				1,735.00	499.43
				Total Parts (S\$)	5,495.00	1,578.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	500.00
2	PANEL BEATING ON AFFECTED AREAS	New	800.00	400.00
3	REMOVE AND REFIR REAR UPHOLSTERY SEAT ETC	New	300.00	60.00
4	REMOVE AND REPAIR REAR BUMPER SENSOR	New	100.00	50.00
5	REAR CHASSIS ALIGNMENT RH	New	200.00	0.00
6	TO CHECK ELECTRICAL WIRING	New	100.00	20.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	50.00	30.00
		Gross Labour Cost (S\$)	2,350.00	1,060.00
	Report was unsubm	itted during this print-out.		

< END OF ESTIMATES >