

Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore 60 Jalan Lam Huat #01-22/23 Carros Centre Singapore 737869 GST Reg no. 201629414D Hotline: 6385 1171

Our reference:

23 - 171317

Date:

19-06-2023

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

Dear Sirs

RE:

Road Traffic Accident on 29/6/2022

Ng Fern Lan

In accordance with your instructions received in this office on

1/7/2022

, we made arrangements to

examine the vehicle on

1/7/2022

at above-mentioned address. The following data was

recorded:

Vehicle details

Make	Skoda	Registration	SNB7172P
Model	Octavia RS 2.0 TSI AIDISPLAY Chassis TMBBU7NE9L00		TMBBU7NE9L0047297
Colour	Black	Gearbox	Auto
Odometer	32648km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	245/40R18	85% Dunlop				
Front right	245/40R18	85% Dunlop				
Rear left	245/40R18	85% Dunlop				
Rear right	245/40R18	85% Dunlop				

Status	REPAIRABLE		
Magnitude	Medium		
Legal status	Unroadworthy		

Impact Direction & Area of Damage:



Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore 60 Jalan Lam Huat #01-22/23 Carros Centre Singapore 737869 GST Reg no. 201629414D Hotline: 6385 1171

Our reference:

23 - 171317

Date:

19-06-2023

Page

2

Section A: Damaged Parts Assessment

Section A. Dam	Section A: Damaged Parts Assessment Condition As Repairer's Our						
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Adjustment			
List Items :							
Front bumper	1	deformed	1640.00	1640.00 🗸			
Front bumper side retainer @\$68.00	2	deformed	136.00	136.00 ✓			
Front bumper LED fog lamp lh	1	intact.refix	638.00	0.00 × nn			
Front bumper fog lamp grille @\$93.70	2	Ih grazed.torn rh refix	187.40	93.70 × nn			
Front bumper foglamp trim @\$72.00	2	Ih grazed.torn rh refix	144.00	72.00 × nn			
Front bumper sponge	1	torn	198.00	198.00 🗸			
Front bumper reinforcement	1	bent	768.00	768.00 X nn			
Front bumper tow cover	1	refix	25.00	0.00 × nn			
Front bumper lower grille	1	grazed.torn	235.00	235.00 × nn			
Front bumper parking sensors @\$221.00		2pcs malfunction	884.00	442.00 🗸			
Front bumper parking sensor retainer @\$15.00	4	necessary	60.00	60.00 🗸			
Headlamp @\$2390.00	2	grazed.cracked	4780.00	4780.00 X nn			
Headlamp bracket @\$125.00	2	deformed	250.00	250.00 🗸			
Front grille	1	cracked	312.00	312.00 ✓			
Front grille emblem 'vRS'	1	necessary	70.40	70.40 🗸			
Front grille trim	1	cracked	152.00	152.00 🗸			
Bonnet	1	buckled	1850.00	1850.00 🗸			
Bonnet emblem	1	cracked	83.00	83.00 🗸			
Bonnet lock	1	check.serviceable	145.00	0.00 × nn			
5	Sub- Tota	al cost	12557.80	11142.10 5193.4			
Percentage di	scount:	10%	1255.78	1114.21 -10%			
		ts for parts	11302.02	10027.89 4674.0			
Special Nett Items:							
Front number plate with casing	1	cracked	50.00	50.00 40			
Front bumper clip	set	necessary	50.00	50.00 30			
	otal cos	ts for parts	100.00	100.00 70			
Parts Repair							
*	*	*	0.00	0.00			
s	ub- Tota	al costs	0.00	0.00			
Tot	al costs	for parts	11402.02	10127.89			

Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore

60 Jalan Lam Huat #01-22/23 Carros Centre Singapore 737869 GST Reg no. 201629414D

Hotline: 6385 1171

Our reference:

23 - 171317

Date

19-06-2023

Page

3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total		1
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.		16	\$	720.00	40
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work. \$		\$	500.00	400
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$	30.00	V
Remove and replace front bumper reverse sensor & conduct distance safety setting.	\$ 45.00	1.7	\$	76.50	30
Specialist charges - Check/Diagnostic and reprogramming			\$	150.00	100
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$ 45.00	1	\$	45.00	×
9.30	Total I	abour cost	\$	1,521.50	J 96

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

5704.06

4 days

L/S - 4563.24 = 4550