



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 777C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DENTED / TWISTED	1,128.00	600.00
1	FRONT FENDER RH	DENTED / BUCKLED	1,410.00	600.00
1	FRONT FENDER WHEEL ARCH RH	DENTED / DEFORMED	1,057.50	500.00
1	HEADLAMP FINISHER RH	DENTED / DEFORMED	399.50	250.00
			3,995.00	1,950.00
LABOUR				
	LABOUR TO REPAIR & REPLACE DAMAGED PARTS.		1,000.00	500.00
	SPRAY PAINTING ON AFFECTED AREA.		1,000.00	600.00
	CHECK WIRING SYSTEM & REFOCUS HEADLAMP.	NOT NECESSARY	50.00	-
			2,050.00	1,100.00
GRAND TOTAL			6,045.00	3,050.00
RECOMMENDED COST OF REPAIRS				3,050.00

Report Ref No. CS3/HSB23002183/Rqp3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.