

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23006944/TNY3E2
Date: 18/07/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000847
Claimant Vehicle No :	SHD4682P	Insured Vehicle No :	SNG2064A
Date of Loss:	06/07/2023	Nature of Claim:	TP
		Claim No:	M2303913

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4682P	Engine No:	G4LEKU408617
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU189899
Reg. Date:	14/11/2019 (Man. Year: 2019)	Odometer:	318061 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	4,087.44	3,739.20	348.24	8.52	
Miscellaneous Items	11.00	11.00	0.00	0.00	
Labour	2,030.00	1,295.00	735.00	36.21	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	6,128.44	5,045.20	1,083.24	17.68	
Approved Total (Overridden) (S\$)		4,050.00			
	(S\$)	6,128.44	4,050.00	2,078.44	33.91
	+ GST 8.00/8.00% (S\$)	490.28	324.00	166.28	33.92
	Nett Amount (S\$)	6,618.72	4,374.00	2,244.72	33.91

INSPECTION

Date of Assignment:	10/07/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	10/07/2023	Inspected At:	59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2023)
Parts: 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD4682P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	459.40 FL	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER BEAM	Not Necessary	394.80 FL	*- FL
4	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
5	1		*REAR FOG LAMP ASSY	Cut	201.50 FL	*201.50 FL
6	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL
7	1		*REAR BUMPER TOW COVER	Deformed	98.80 FL	*98.80 FL
8	1		*BOOTLID COVER	Bent	2,549.70 FL	*2,549.70 FL
9	1		*BOOTLID EMBLEM - IONIQ	Necessary	31.30 FL	*31.30 FL
10	1		*BOOTLID EMBLEM - HYBRID	Necessary	24.30 FL	*24.30 FL
11	1		*BOOTLID EMBLEM - H	Cut	28.00 FL	*28.00 FL
12	1		*BOOTLID GLASS LOWER MOULDING	Necessary	145.20 FL	*145.20 FL
13	1		*BOOTLID GLASS UPPER MOULDING	Necessary	186.30 FL	*186.30 FL
14	1		*REAR NUMBER PLATE	Cracked	55.00 F	*55.00 F
15	1		*REAR BOOTLID COMFORT LOGO	Necessary	30.00 F	*30.00 F
16	1		*REAR BOOTLID COMFORT TEL NOS. LOGO	Necessary	30.00 F	*30.00 F
17	1		*REAR BOOTLID APPS LOGO	Necessary	40.00 F	*40.00 F
18	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 F	*46.00 F
19	1		*REVERSE SENSOR	Not Working	180.00 F	*180.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,014.05	4,578.75
- List Item Discount on L Items 20.00/20.00% (S\$)	926.61	839.55
Total Parts (S\$)	4,087.44	3,739.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,100.00	525.00
2	SPRAY PAINT	New	600.00	500.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	30.00
5	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
6	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
7	TOWING CHARGE	New	60.00	60.00
			Gross Labour Cost (\$)	2,030.00
				1,295.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >