

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	HSBC LIFE (SINGAPORE) PTE LTD		Ref:	CS3/HSB23006953/Tnp3m4
		EVARD #48-01 MARINA BAY RE TOWER 2 SINGAPORE	Date	17/07/2023
	ATTN: LOW GARN	ET	Code	: HSB
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SHA 2729T	Veh. Inspected	GBM 3922C
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S3M04NXS	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	10/07/2023
2. Vehicle Particulars & Condition				
	Make & Model	DFSK EC31	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2023
	Chassis No.	LVP1PB4B4NC894093	Colour	SILVER
	Odometer	3397 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/R14	MAXTREK	6 mm
	L/H Front Tyre	185/R14	MAXTREK	6 mm
	R/H Rear Tyre	185/R14	MAXTREK	6 mm
	L/H Rear Tyre	185/R14	MAXTREK	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5.	General Information			
	Accident Date	07/07/2023	Inspect Date / Time	10/07/2023 (03:30 PM)
	Survey held at	PAUL HOE BATTERIES & MOTO	OR SERVICES	
		BLK 1 KAKI BUKIT AVE 6 #01-109 AUTOBAY SINGAPORE 417833		
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,500-\$7,500			
5b.	Estimate Days of Repair			
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	7 Wo	rking Days
	Report Ref No. CS3/HSB23006953/Tnp3m4			

Report Ref No. CS3/HSB23006953/Tnp3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser