

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance Management)
Singapore 068897

Our File No: CS/AIS23006995/UNP3E2**Date:** 26/07/2023**REFERENCE**

Insured/Claimant:	LEE CHONG	Policy No:	SP2002092755	
Date of Loss:	08/07/2023	Nature of Claim:	OD	Claim No: 202332010463

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE512X	Engine No:	2ARF213122
Make & Model:	LEXUS ES250, 2.5 (A)	Chassis No:	JTHBJ1GG702092712
Reg. Date:	13/07/2016 (Man. Year: 2016)	Odometer:	127652 km
Colour:	Silver		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 7 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,189.06	3,265.95	12,923.11	79.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	1,930.00	2,070.00	51.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,189.06	5,195.95	14,993.11	74.26
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	19,689.06	4,695.95	14,993.11	76.15
+ GST 8.00/8.00% (S\$)	1,575.12	375.68	1,199.44	76.15
Nett Amount (S\$)	21,264.18	5,071.63	16,192.55	76.15

INSPECTION

Date of Assignment:	11/07/2023	
Date Inspected:	12/07/2023	Inspected At: Specialist Motor Pte Ltd (HQ) BLK 3018A UBI ROAD 1 #01-24-26 Singapore 408711
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2023)
Parts:	143	LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE512X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH (WCP)	Distorted	380.00 F	*380.00 F
2	1		*FRONT FENDER COWLING LH (WCP)	Torn	130.00 F	*130.00 F
3	1		*FRONT FENDER COWLING CLIPS LH (WCP)	Necessary	15.00 F	*15.00 F
4	1		*HEADLAMP ASSY LH (WCP)	Cracked	1,500.00 F	*1,500.00 F
5	1		*FRONT BUMPER FASCIA (WCP)	Torn	370.00 F	*270.00 F
6	1		*SET FRONT BUMPER CLIPS (WCP)	Necessary	15.00 F	*15.00 F
7	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Cracked	40.00 F	*40.00 F
8	1		*FRONT BUMPER FOG LAMP CHROME LH (WCP)	Serviceable	75.00 F	*- F
9	1		*FRONT BUMPER FOG LAMP ASSY LH (WCP)	Not Necessary	110.00 F	*- F
10	1		*FRONT FENDER GARNISH LH (WCP)	Serviceable	85.00 F	*- F
11	1		*FRONT SUPPORT PANEL (WCP)	Repair	560.00 F	*- F
12	1		*RADIATOR TOP GARNISH (WCP)	Not Necessary	140.00 F	*- F
13	1		*SET RADIATOR TOP GARNISH CLIPS (WCP)	Not Necessary	15.00 F	*- F
14	1		*FRONT WHEEL HOUSE PANEL LH (WCP)	Repair	350.00 F	*- F
15	1		*FRONT SHOCK ABSORBER LH (WCP)	Not Necessary	350.00 F	*- F
16	1		*FRONT WHEEL BEARING (WCP)	Not Necessary	70.00 F	*- F
17	1		*FRONT KNUCKLE ARM LH (WCP)	Not Necessary	350.00 F	*- F
18	1		*FRONT WHEEL HUB LH (WCP)	Not Necessary	100.00 F	*- F
19	1		*FRONT LOWER ARM LH (WCP)	Not Necessary	150.00 F	*- F
20	1		*FRONT DRIVE SHAFT ASSY LH (WCP)	Not Necessary	2,005.20 F	*- F
21	1		*STEERING RACK & PINION ASSY (WCP)	Not Necessary	750.00 F	*- F
22	1		*FRONT VIEW MIRROR ASSY LH (WCP)	Repair	2,269.90 F	*- F
23	1		*FRONT BUMPER SIDE SUPPORT LH (WCP)	Not Necessary	180.00 F	*- F
24	1		*FRONT GRILLE (WCP)	Not Necessary	520.00 F	*- F
25	1		*FRONT GRILLE CHROME (CRACKED)(WCP)	Not Consistent With The Impact	130.00 F	*- F
26	1		*FRONT WHEEL RIM LH (LOCAL REPAIR)	Cut	3,502.00 FS	*500.00 FS
27	1		*FRONT WHEEL TYRE LH	Serviceable	780.00 FS	*- FS
28	1		*SIDE MIRROR LAMP LH (WCP)	Scratched	65.00 F	*65.00 F

Report was unsubmitted during this print-out.

7/26/23, 10:26 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*BONNET HINGE LH (WCP)	Bent	45.00 F	*45.00 F
30	1		*FRONT FENDER BRACE BRACKET LH (WCP)	Bent	50.00 F	*50.00 F
31	1		*FENDER TRIM CLIPS (WCP)	Necessary	2.50 F	*2.50 F
32	1		*FRONT FENDER SEAL CLIPS (WCP)	Necessary	2.00 F	*2.00 F
F=Franchise part. S=SpcNett.						
Sub Total (S\$)					15,106.60	3,014.50
+ Margin on L,N Items 10.00/10.00% (S\$)					1,082.46	251.45
Total Parts (S\$)					16,189.06	3,265.95
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	180.00	130.00
2	CUT OUT, RENEW, KNOCKING & WELDING FRONT FENDER LH, FRONT WHEEL HOUSE PANEL LH, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY	New	1,400.00	800.00
3	REMOVE & INSTALL FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	480.00	0.00
4	COMPUTERISE WHEEL ALIGNMENT	New	180.00	80.00
5	SPRAY PAINTING ON DAMAGE PARTS	New	1,680.00	900.00
6	CHECK ALL LIGHTING AFTER REPAIRS	New	80.00	20.00
Gross Labour Cost (\$\$)			4,000.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >