



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 2428A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	696.00	696.00
1	FRONT LH BUMPER SIDE RETAINER	DISTORTED	63.00	63.00
1	FRONT LH HEAD LAMP ASSY	CUT	1,975.32	1,675.00
1	FRONT (LH) FENDER	BENT	385.00	385.00
1	FRONT (LH) FENDER GARNISH	DISTORTED	118.00	118.00
1	SET FRONT BUMPER CLIP	NECESSARY	55.00	55.00
1	FRONT LH FENDER DUST COVER	REPEATED	283.00	-
	LESS 10% DISCOUNT		-357.53	-299.20
			3,217.79	2,692.80
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT (LH) SPORT RIM (SN)	SERVICEABLE	250.00	-
			250.00	-
	<u>LABOUR</u>			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.		650.00	400.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON :- DAMAGE PORTION.		750.00	440.00
	CHECK WIRING.		30.00	20.00
			1,430.00	860.00
	GRAND TOTAL		4,897.79	3,552.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,850.00

Report Ref No. CS/SMR23006996/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.