

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 5805T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	580.20	561.30
1	REAR BUMPER SIDE RETAINER LH	BENT	89.10	89.10
1	REAR BUMPER BRACKET LH	CRACKED	91.80	91.80
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	67.20	-
1	REAR BUMPER BEAM	NOT NECESSARY	547.90	-
1	REAR BUMPER SENSOR	NOT NECESSARY	405.10	-
1	REAR TAILLAMP LH	CRACKED	1,042.80	1,042.80
1	REAR TAILLAMP PANEL	TO REPAIR SEE LABOUR	528.10	-
1	REAR BOOT AIRDUCT MOULDING	NOT NECESSARY	98.50	-
1	REAR FENDER SPLASH GUARD LH	NOT NECESSARY	132.00	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	982.80	-
	LESS 25% DISCOUNT		-	-446.25
			4,565.50	1,338.75
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR FENDER SPLASH GUARD LH CLIPS (SN)	NOT NECESSARY	30.00	-
			60.00	30.00
	LABOUR			
	TO CARRY OUT ANTI-RUST TREATMENT.	NOT NECESSARY	120.00	-
	REWIRING TO FACILITATE WORKS.		120.00	20.00
	REMOVE AND REFIT ALL TRIMS, UPHOLDERS, GARNISH AND ALL NECESSARY TO FACILITATE REPAIR WORKS.		320.00	60.00
	LABOUR TO REMOVE AND REPLACE DAMAGED PARTS (INCLUDING REFITTING AND REPOSITIONING OF REPLACED PARTS). INCLUSIVE OF THE REPAIR OF REAR TAILLAMP PANEL AND REAR FENDER LH.		850.00	380.00
	SPRAY PAINTING MATERIALS AND RESPRAY OF ALL AFFECTED AND REPLACED PARTS NECESSARY FOR PAINTWORK.		800.00	400.00
			2,210.00	860.00
	GRAND TOTAL		6,835.50	2,228.75

Report Ref No. CS/FCI23007018/Uqy3m4





RECOMMENDED COST OF LUMP SUM REPAIRS		1,750.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/FCI23007018/Uqy3m4

CHUA KANG SENG

Licensed Appraiser