

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/FC123007018/4943

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SM Q 5805T

at Workshop m/s huot hock

of

Insured: GSK 45764

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: 892k

IDAC Accident Rpt: Consistent? : **Yes or No**

GIA / PR Seen: Consistent? : **Yes or No**

Est. Repairs: 3 days Res.: **Yes or No**

Lum Sum: 20 % 3 Val.: **Yes or No**

CA / REV / REP. / 24 HRS

718f

Date: _____ Person Contacted: L7A 35108

Vehicle: **IN / OUT**

Veh No: SM Q 5805T Yr Regn: 25/11/19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota Corolla Altis 1598

Colour: silver A/C: **Insured / Std / NI / NA**

Sp. Reading: 54859 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: MR2B E BE 100003034

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/55-R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or continental

Front

7

Rear

7

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 09/07/23

D.O.I. 12/7/23

Survey held at _____

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or

N/S Rear

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time Action / Instruction

20/7/23

7:11am 1062-30

4/5 1750 inbound Ben Cred @ 5085.50, 74%

Date/Time, File Pass to?

☐

: **Preli. Report**

1) 24/7 typist

☐

: **Final Report**

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format : TP

Lump Sum / I.B.I: (\$ 1750)

發 福 摩 哆 車 房
HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO 375654/00C

not added
her
2/5/1750/
3 days
take phle after
reg
12/7/23

Carplate: SMQ5805T

Chassis No: ZRE210R-GEXGPZ

Accident Date: 09/07/2023

Make & Model: Toyota Altis

1st price

[illegible]

No.	All Necessary Work	Price	✓/✗	Remarks
1	To Carry Out Anti-rust Treatment	\$ 120.00		~x
2	Rewiring to Facilitate Works	\$ 120.00		20
3	Remove and Refit All Trims, Upholders, Garnish and All Necessary to Facilitate Repair Works	\$ 320.00		60
4				
5				
6				
7	Labour to remove and replace damaged parts (Including refitting and repositioning of replaced parts)	\$ 850.00		380
8	Spray painting materials and respray of all affected and replaced parts necessary for paintwork	\$ 800.00		400
	Estimated No. of days for repairs and respray of all necessary	6 Days 3		

68 35.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 1785
252
1338.75
30
860
2228.75
202
1183