8/3/23, 4:12 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG23007022/KQY3M4

Date: 03/08/2023

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001894039

Claimant Vehicle SMV746L Insured Vehicle No: SJB2259D

Date of Loss: 08/07/2023 Nature of Claim: TP Claim No: 321712

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMV746L

Make & Model:TOYOTA NOAH HYBRID, 1.8 X CVT (A)Engine No:2ZR2G55019Reg. Date:15/09/2020 (Man. Year: 2020)Chassis No:ZWR800430221Colour:Metallic MaroonOdometer:180231 km

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Farroad 3 mm Rear Left Side: Farroad 9 mm
Front Right Side: Farroad 3 mm Rear Right Side: Farroad 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|-----------------------------------|------------|------------|------------|--------|
| Parts | | 2,087.85 | 1,300.57 | 787.28 | 37.71 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 1,400.00 | 650.00 | 750.00 | 53.57 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 3,487.85 | 1,950.57 | 1,537.28 | 44.08 |
| | Approved Total (Overridden) (S\$) | | 1,550.00 | | |
| | Nett Amount (S\$) | 3,487.85 | 1,550.00 | 1,937.85 | 55.56 |

INSPECTION

Date of Assignment: 12/07/2023

LIAN HER MOTORS

Date Inspected: 20/07/2023 Inspected At: BLK 5038 ANG MO KIO INDUSTRIAL PARK 2,

#01-405 SINGAPORE 569541

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

8/3/23, 4:12 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Aug 2023)

Parts: M1-MPV TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMV746L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------|-----------|----------------|--|--------------------|-------------|--------------|
| 1 | 1 | | *FRONT TOP GRILLE COVER CHROME MOULDING | Serviceable | 155.80 FL | *- FL |
| 2 | 1 | | *FRONT GRILLE CENTRE COVER | Serviceable | 225.60 FL | *- FL |
| 3 | 1 | | *FRONT GRILLE CENTRE COVER CHROME MOULDING | Serviceable | 155.80 FL | *- FL |
| 4 | 1 | | *FRONT LOWER GRILLE | Mtg Cracked | 276.10 FL | *276.10 FL |
| 5 | 1 | | *FRONT GRILLE LOWER COVER | Mtg Cracked | 222.80 FL | *222.80 FL |
| 6 | 2 | | *FRONT GRILLE LOWER COVER CHROME MOULDING | Necessary | 210.20 FL | *210.20 FL |
| 7 E=Era | 1 | part. L=ListIt | *FRONT BUMPER | Mtg Cracked | 1,537.50 FL | *1,025.00 FL |
| 1 –1 10 | 111011130 | part. L-Lioti | ionibio. | Sub Total (S\$) | 2,783.80 | 1,734.10 |
| | | | - List Item Discount on L Items | 25.00/25.00% (S\$) | 695.95 | 433.53 |
| | | | | Total Parts (S\$) | 2,087.85 | 1,300.57 |
| | | | Report was unsubmitted during this print | t-out. | | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount | | | | |
|---|--|----------|------------|--------|--|--|--|--|
| Lab | <u>Labour Items</u> | | | | | | | |
| 1 | REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING | New | 700.00 | 250.00 | | | | |
| 2 | TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION | New | 700.00 | 400.00 | | | | |
| | Gross Labour Cost (S\$) | | 1,400.00 | 650.00 | | | | |
| Report was unsubmitted during this print-out. | | | | | | | | |

< END OF ESTIMATES >