

## AUTOMOBILE ASSESSMENT REPORT

TO: LIM CHEE KEONG  
C/O: MOTOCRAFT  
7 SOON LEE STREET  
#01-18 SINGAPORE 627608

Our Reference: 0822/MC246  
Date: 20-Sep-2022

### ASSESSMENT OF VEHICLE NO. FW 7432 Z

DATE OF LOSS: 27-Aug-2022

We have carried out a physical assessment at **MOTOCRAFT**,  
7 Soon Lee Street, 01-18 Singapore 627608, according to your instruction  
on **29-Aug-2022** and are pleased to submit our report herewith.

### 1. VEHICLE PARTICULARS

Registration No.:	FW 7432 Z
Make & Model:	HONDA WAVE 125S
Year of Registration:	2003
Engine Capacity:	125
Chassis No.:	NF125MD0058409
Engine No.:	NF125MDE0058409
Colour:	BLUE

### 2. VEHICLE CONDITION

Body Paint:	GOOD
Steering:	SERVICEABLE
Foot Brake:	SERVICEABLE
Parking Brake:	SERVICEABLE
Modification:	NIL

### 3. TYRE PARTICULARS & CONDITION

Front  
Make/Size/Thread: MAXXIS 70/90 R17 – 70%

Rear  
Make/Size/Thread: MAXXIS 80/90 R17 – 70%


#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the REAR portion.

#### 5. REMARKS

Market Value: Na  
Salvage Value: Na  
Repair Limit: Na

Estimated Amount: \$5,625.30  
Adjusted Amount: \$4,459.60  
Lump Sum: **\$3,200.00**  
Estimated Repair Days: 8 days  
Date of Completion : 05-Sep-2022



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a **"Without Prejudice"** basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

### ASSESSMENT REPORT FOR VEHICLE NO. FW 7432 Z

#### PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	SIDE MIRROR L/R - SET	Cracked	118.00	118.00 70 ✓
1	HEADLAMP ASSY	Cracked	238.00	238.00 ✓
2	FRONT SIGNAL L/R	Cracked	108.00	108.00 54 ✓
1	HANDLE BAR	Bent	108.00	108.00 ✓
1	HANDLE GRIP L/R - SET	Cut	68.00	68.00 ✓
1	HANDLE LEVER RH	Cracked	78.00	78.00 ✓
1	FRONT FORK ASSY	Bent	422.00	422.00 ✓
1	FRONT FENDER	Cracked	148.00	148.00 ✓
1	FRONT WHEEL	Bent	285.00	285.00 X nn
1	FRONT WHEEL BEARING	Jammed	88.00	88.00 38 ✓
1	FRONT BRAKE ROTOR	Bent	118.00	118.00 ✓
1	FRONT RH FOOTREST	Bent	68.00	68.00 40 ✓
1	FRONT FOOTREST BRACKET	Bent	98.00	98.00 ✓
1	FRONT RH FOOT BRAKE PEDAL	Bent	98.00	98.00 42 ✓
1	CENTRE BASKET CARRIAGE	Bent	115.00	115.00 35 ✓
1	FULL BODY COWLING COVERSET	Cracked	520.00	520.00 185 ✓
1	REAR RH FOOTREST	Bent	68.00	68.00 40 ✓
1	REAR RH FOOTREST BRACKET	Repair	98.00	- X nn
1	REAR WHEEL	Repair	285.00	- X nn
1	REAR FENDER	Repair	228.00	- X nn
1	EXHUAUST PROTECTOR COVER	Bent	98.00	98.00 ✓
1	EXHAUST PIPE	Repair	362.00	-

1880  
-10%  
1692

Less 10% discount  
Parts Total:

3,817.00	2,844.00
381.70	284.40
3,435.30	2,559.60

### ASSESSMENT REPORT FOR VEHICLE NO. FW 7432 Z

#### SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE	Bent	25.00	25.00 ✓
1	REAR TOP BOX	Cracked	185.00	185.00 ✓

<b>210</b> Special Nett Total :	210.00	210.00
---------------------------------	--------	--------

#### LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To provide towing charge.	50.00	50.00 ✓
2	Check wiring system and light.	80.00	60.00 30
3	Wheel alignment.	100.00	80.00 50
4	To check, align and balance body main frame.	250.00	200.00 150
5	Spray painting.	600.00	500.00 200
6	Labour for repair and replace parts.	900.00	800.00 250
		730	Labour Total : 1,980.00 1,690.00
		<b>TOTAL (PARTS &amp; LABOUR) \$</b>	<b>5,625.30 4,459.60</b>

**2632**

**L/S - 2105.60  
= 2100**

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

**\$3,200.00**

**(SINGAPORE DOLLARS THREE THOUSAND TWO HUNDRED ONLY)**

**3 days**



Amas Ong  
Automobile Assessor