

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22008366/Ecy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	23/11/2022		
	ATTN: LOH CYNTH	AIA		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 7480J	Veh. Inspected	k	FW 7432Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M049V2	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		29/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA WAVE 125S	c.c		125	
	Engine No.	HIDDEN	Year of Reg.		2003	
	Chassis No.	NF125MD0058409	Colour		BLUE	
	Odometer	42920 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	60/70-17	DUNLOP		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	70/80-17	DUNLOP		4 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.					
5.	5. General Information					
	Accident Date	27/08/2022	Inspect Date /	Time	29/08/2022 (05:26 PM)	
	Survey held at	MOTOCRAFT PTE LTD				
	7 SOON LEE STREET #01-18 SINGAPORE 627608					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM22008366/Ecy3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser