

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01 (Claims & Performance Management)  
Singapore 068897

**Our File No:** CS/AIS23007047/UNP3Q2**Date:** 27/07/2023**REFERENCE**

Insured/Claimant:	KOH BOON CHUAN GABRIEL	Policy No:	SP2005237661-01
Date of Loss:	08/07/2023	Nature of Claim:	OD
		Claim No:	202332010469

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJD7461S</b>	Engine No:	1ZZ3078534
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100404338
Reg. Date:	01/04/2008 (Man. Year: 2008)	Odometer:	263740 km
Colour:	Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	S\$48,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,869.50	5,470.00	1,399.50	20.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,320.00	1,280.00	49.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,469.50</b>	<b>6,790.00</b>	<b>2,679.50</b>	<b>28.30</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,400.00</b>		
<b>- Excess (\$\$)</b>	0.00	600.00	-600.00	
<b>(\$\$)</b>	9,469.50	4,800.00	4,669.50	49.31
<b>+ GST 8.00/8.00% (\$\$)</b>	757.56	384.00	373.56	49.31
<b>Nett Amount (\$\$)</b>	<b>10,227.06</b>	<b>5,184.00</b>	<b>5,043.06</b>	<b>49.31</b>

**INSPECTION**

Date of Assignment:	12/07/2023	Present Location:	Falcon-Air Auto Services Pte Ltd (Tampines)
Date Inspected:	13/07/2023	Inspected At:	Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	5.0 days		

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD7461S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented / Buckled	510.00 F	*510.00 F
2	2		*BONNET HINGES	Repair	120.00 F	*- F
3	1		*BONNET LOGO	Not Necessary	60.00 F	*- F
4	1		*BONNET CHROME MOULDING	Cracked	190.00 F	*190.00 F
5	1		*BONNET INSULATOR	Not Necessary	190.00 F	*- F
6	10		*BONNET INSULATOR CLIPS	Necessary	40.00 F	*40.00 F
7	1		*BONNET LOCK	Twisted	90.00 F	*90.00 F
8	1		*BONNET RUBBER SEAL	Necessary	30.00 F	*30.00 F
9	1		*FRONT BUMPER	Torn	480.00 F	*480.00 F
10	2		*FRONT BUMPER SIDE RETAINER	Bent / Necessary	120.00 F	*120.00 F
11	1		*RADIATOR GRILLE	Torn	140.00 F	*140.00 F
12	2		*RADIATOR GRILLE STOPPER CLIPS	Necessary	40.00 F	*40.00 F
13	1		*FRONT NUMBER PLATE	Bent	45.00 F	*40.00 FS
14	1		*FRONT BUMPER SPONGE	Not fitted	110.00 F	*- F
15	1		*FRONT BUMPER REINFORCEMENT	Bent	240.00 F	*240.00 F
16	1		*HEADLAMP	N/S Cracked	1,560.00 F	*780.00 F
17	1		*BRACE PANEL	Twisted	120.00 F	*120.00 F
18	1		*FRONT SUPPORT PANEL	Bent / Twisted	600.00 F	*600.00 F
19	1		*AIR-CON CONDENSER	Bent / Punctured	750.00 F	*750.00 F
20	1		*RADIATOR	Bent / Cracked	770.00 F	*770.00 F
21	1		*COOLANT	Necessary	40.00 F	*40.00 FS
					Sub Total (S\$)	6,245.00 4,980.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	624.50 490.00
					Total Parts (S\$)	6,869.50 5,470.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND FOCUS HEADLAMP	New	50.00	20.00
2	TO VACCUM,RE-OIL AND RENEW AIR-CON GAS	New	150.00	100.00
3	TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL, REPAIR INNER PANEL, REWELD INNER PANEL,REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	New	1,000.00	600.00
4	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	1,400.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,600.00</b>	<b>1,320.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >