

A&S, P&C, BY:

REF:

CC3/CTI23007050/Dpa³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

DAG Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STD 3413 G Yr Regr: Aug 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 CC 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 1383646 T/Radio: Insured / Std / NI / NAEng/No: D4FDGU652941C/No: KMHLEB41UMGU093371Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16R: 11

BS / DUN / EXNOVA / GY / FS / LZA / MEC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal: S mm R/Bal: S mmL/Bal: S mm L/Bal: S mmD.O.A. 28/06/2023 D.O.I. 30/06/2023Survey held at CDGB LuyangDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>China Triping GBH 2934.B</u>
<u>13/07/23</u>	<u>Insure 2/5 5,100/- within 4 days of 'in'</u>

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

: Prel. Report

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

: Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

S + RS \$

Photos

Others

Report Format: _____

I union from 11:15 to 12:00

COMFORTDELGRO ENGINEERING PTE LTD

P1/2

REPAIR ESTIMATE

DATE: 30.06.2023

3P INSURANCE: CHINA TAIPING (45)

MODEL: HYUNDAI I40

SURVEYOR LKK-

VEH NO.: SHD3413G

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Bootlid <i>Denki</i>	1		\$2,609.80 ✓
	Bootlid Hinge (LH/RH) <i>HH</i>	2	\$142.30	284.60 X
	Bootlid Lock Upper <i>Denki</i>	1		\$114.90 ✓
	Bootlid Lock Lower <i>Denki</i>	1		\$31.70 X
	Bootlid Hyundai Plate <i>HH</i>	1		\$21.10 ✓
	Bootlid 'H' Emblem <i>HH</i>	1		\$63.10 ✓
	Bootlid CRDI Plate <i>HH</i>	1		\$52.40 ✓
	Bootlid I40 Emblem <i>HH</i>	1		\$67.90 ✓
	Bootlid Lamp (LH/RH) <i>o/s crane 4/5 HH</i>	2	\$622.20	\$1,244.40 ✓
	Bootlid Moulding <i>HH</i>	1		\$85.00 ✓
	Bootlid Lower Outer Garnish <i>Denki</i>	1		\$227.90 ✓
	Rear Bumper <i>Denki</i>	1		\$553.00 ✓
	Rear Bumper Reinforcement <i>2 HH</i>	1		\$428.40 X
	Rear Bumper Clip (10 pcs) <i>HH</i>	10	\$2.20	\$22.00 ✓
	Rear Bumper Side Bracket RH/LH <i>HH</i>	2	\$80.30	\$160.60 X
	Rear Bumper Sponge <i>2 Svc</i>	1		\$119.50 X
	Rear Bumper Under Cover <i>brown</i>	1		\$228.00 ✓
	Rear Bumper Reflector RH / LH <i>HH</i>	2	\$32.00	\$64.00 X
	Tail Lamp (LH/RH) <i>2 HH</i>	2	\$697.80	\$1,395.60 X
	Rear End Panel <i>Denki</i>	1		\$526.70 ✓
	Rear End Lower Panel <i>3 Denki</i>	1		\$495.50 X
	Rear End Panel Garnish <i>2 HH</i>	1		\$57.70 X
	Fuel Lid Cover <i>denki * check consistency</i>	1		\$82.10 X
SPARE PARTS SUB TOTAL				\$ 8,935.90
LESS 20%				\$ 1,787.18
DISCOUNTED SPARE PARTS TOTAL				\$ 7,148.72

5194.00

4155.20 =

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
			SHD3413G	PAGE 2 of 2
	Bootlid ComfortDelGro Hec	1		\$30.00 ✓
	Bootlid 65521111 Hec	1		\$30.00 ✓
	Reverse Sensor Dam	1		\$135.70 ✓
	Rear Bumper Mat HF	1		\$50.00 X
	Rear Fender Adv.Sticker RH / LH Hec	2	\$100.00	\$200.00 ✓
	BootLid Adv.Sticker Hec	1		\$100.00 ✓
	Rear Bumper Adv.Sticker Hec	1		\$50.00 ✓
	NETT TOTAL		545.70 =	\$595.70
	SPARE PARTS & OTHERS TOTAL			\$ 7,744.42
	Panel Beating			\$ 1,200.00 840/-
	Spray Painting Charge			\$ 900.00 750/-
	Wiring Charge			\$ 40.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	LABOUR TOTAL		1700.00 =	\$ 2,360.00
	(REAR) ESTIMATE TOTAL			\$ 10,104.42
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

30/06/2023 @ 1645hr

HA Andrew

2 Panel

Ym 4 days.

LKK Auto

8

6400-90

4/s 5100/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 30.06.2023 15:43

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5902327

JC NO305559277

OMER

S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755
(R) (O)
(P)

UNT CARD NO.


REGN NO: SHD3413G	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 28.06.2023 18:30
YR OF MANU. 25.08.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU093371	COMPLETION DATE/TIME:

cident Date: 28.06.2023
TURE: 3P 28.06.2023

JOB DESCRIPTION

NO LABOR CODE
0010 PB

DESCRIPTION
LUMPSUM REPAIR-SHD3413G-TP



ED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

dgement Slip

Exit Pass

Vehicle No.: SHD3413G

LIMITS

Vehicle No.:

SHD3413G

Service Advisor

Signature/Date

Name of Service Advisor

Date

med to Service Reception upon collection

To be kept by Security Guard