



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4469E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BENT	486.18	486.18
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT FENDER RH	DENTED	1,111.93	1,111.93
1	FRONT FENDER (HYBRID) RH	NECESSARY	86.50	86.50
1	FRONT WHEEL RIM RH	CUT	1,570.55	1,570.55
	LESS 25% DISCOUNT		-819.29	-819.29
			2,457.87	2,457.87
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT WHEEL TYRE RH (SN)	NOT NECESSARY	216.00	-
			216.00	-
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	WHEEL ALIGNMENT.		120.00	60.00
			1,520.00	1,260.00
	GRAND TOTAL		4,193.87	3,717.87
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,950.00

Report Ref No. NS/INC23007058/Dvp3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.