



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFJ 3139R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BONNET (WCP)	BUCKLED	850.00	850.00
2	FRT BONNET HINGE (WCP)	BENT	110.00	110.00
1	FRT BONNET LOCK (WCP)	TWISTED	85.00	85.00
1	FRT GRILLE (WCP)	BROKEN	295.00	295.00
4	FRT GRILLE CLIP (WCP)	NECESSARY	8.00	8.00
1	FRT BUMPER (WCP)	TORN	350.00	350.00
2	FRT BUMPER RETAINER (WCP)	BENT	40.00	40.00
10	FRT BUMPER CLIP (WCP)	NECESSARY	20.00	20.00
1	FRT BUMPER INNER SPONGE (WCP)	TORN	120.00	120.00
1	FRT BUMPER REINFORCEMENT (WCP)	DENTED	320.00	320.00
2	HEADLAMP (WCP)	O/S NOT NECESSARY/ N/S CRACKED	1,100.00	550.00
1	HEADLAMP SUPPORT PANEL (WCP)	CRACKED	450.00	450.00
1	HEADLAMP SUPPORT TOP GARNISH (WCP)	BROKEN	60.00	60.00
8	SUPPORT TOP GARNISH CLIP (WCP)	NECESSARY	16.00	16.00
1	AIRCON CONDENSER (WCP)	PUNCTURE	495.00	495.00
1	RADIATOR (WCP)	BENT	450.00	450.00
1	RADIATOR FAN ASSY (WCP)	NOT NECESSARY	380.00	-
1	AIR DUCT (WCP)	TWISTED	75.00	75.00
1	AIR HOSE (WCP)	NOT NECESSARY	75.00	-
1	AIR CLEANER BOX (WCP)	NOT NECESSARY	195.00	-
2	HEADLAMP LOWER BRACKET (WCP)	N/S CRACKED (1PC ONLY)	50.00	25.00
2	FRT BUMPER SIDE BRACKET (WCP)	N/S CRACKED (1PC ONLY)	40.00	20.00
1	RADIATOR TOP HOSE (WCP)	NOT NECESSARY	30.00	-
1	THROTTLE BODY (WCP)	CRACKED	450.00	450.00
1	AIR FLOW SENSOR (WCP)	NOT NECESSARY	110.00	-
1	FRT LH FENDER INNER COWLING (WCP)	NOT NECESSARY	280.00	-
10	INNER COWLING CLIP (WCP)	NOT NECESSARY	20.00	-
1	NUMBER PLATE GARNISH (WCP)	BROKEN	25.00	25.00

Report Ref No. CS/LPC23007059/Uvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT BUMPER TOP RUBBER SEAL (WCP)	TORN	130.00	50.00
1	INTAKE MANIFOLD (WCP) (ADDITIONAL)	CRACKED	680.00	680.00
	COST PLUS 15%		1,096.35	831.60
			8,405.35	6,375.60
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE (SN)	BROKEN	35.00	35.00
1	RADIATOR COOLANT (SN)	NECESSARY	25.00	20.00
			60.00	55.00
	<u>LABOUR</u>			
	WIRE CHECKING.		30.00	20.00
	REMOVE & REFIX AIRCON AND GAS.		100.00	100.00
	REMOVE & REFIX THROTTLE BODY + MANIFOLD.		150.00	150.00
	LABOUR CHARGE.		700.00	600.00
	SPRAY PAINTING.		700.00	600.00
			1,680.00	1,470.00
GRAND TOTAL			10,145.35	7,900.60
RECOMMENDED COST OF REPAIRS				7,900.60
LESS EXCESS				-
NETT LIABILITY				-

Report Ref No. CS/LPC23007059/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.