

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2182J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	PUNCTURE	553.00	553.00
1	REAR BUMPER UNDER COVER	DISTORTED	228.00	228.00
1	REAR BUMPER SPONGE	SERVICEABLE	119.50	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
2	REAR BUMPER REINFORCEMENT BRACKET RH / LH @ \$80.30	NOT NECESSARY	160.60	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-302.30	-160.60
			1,209.20	642.40
	NETT ITEMS			
1	REAR BUMPER ADV.STICKER (N)	NECESSARY	50.00	50.00
1	REVERSE SENSORS (N)	NOT NECESSARY	135.70	-
	LESS 10% DISCOUNT		-18.57	-5.00
			167.13	45.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER ADV.STICKER (SN)	REPEATED	50.00	-
2	REAR FENDER ADV.STICKER RH/LH @\$100.00 (SN)	NECESSARY	200.00	200.00
			300.00	250.00
	<u>LABOUR</u>			
	PANEL BEATING.		300.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	R/I REVERSE SENSORS.		120.00	40.00
			720.00	570.00
	GRAND TOTAL		2,396.33	1,507.40





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,200.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC23007061/Dnp3e2

ANG BRYAN TANI

**Automotive Assessor / Investigator** 

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**