



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 2355T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT	TO REPAIR SEE LABOUR	1,566.00	-
1	REAR BOOT RUBBER	NOT NECESSARY	198.00	-
1	REAR BOOT LOCK	NOT NECESSARY	286.00	-
1	REAR BOOT EMBLEM 'KIA'	NOT NECESSARY	89.00	-
1	REAR BOOT EMBLEM 'FORTE'	NECESSARY	86.00	86.00
1	REAR BOOT EMBLEM 'KOUPI'	NECESSARY	92.00	92.00
1	REAR BUMPER	DENTED / TORN	838.00	838.00
2	REAR BUMPER NUMBER PLATE LAMPS @\$39.00	CRACKED	78.00	78.00
1	REAR BUMPER DIFFUSER	CUT	439.00	439.00
2	REAR BUMPER PDC SENSOR @\$205.00	MALFUNCTION	410.00	410.00
1	REAR BUMPER REINFORCEMENT	CRACKED	559.00	559.00
3	REAR BUMPER REINFORCEMENT LOWER BRACKET @ \$18.00	NOT NECESSARY	54.00	-
2	REAR BUMPER SIDE RETAINER - RH / LH @\$85.00	NOT NECESSARY	170.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	596.00	-
1	REAR END PANEL GARNISH	NOT NECESSARY	192.00	-
	LESS 10% DISCOUNT		-565.30	-250.20
			5,087.70	2,251.80
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR NUMBER PLATE WITH CASING (SN)	BENT	50.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	40.00
			95.00	80.00
<u>LABOUR</u>				
	TO KNOCK OUT DENT, CUT / WELD REAR PANEL AND REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOT AND REAR END PANEL.		800.00	600.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		1,000.00	600.00
	TO CHECK WIRING.		30.00	20.00
	TO REMOVE AND REFIX CUSHION AND INNER TRIM.		120.00	80.00

Report Ref No. CS/AGI23007062/Uqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFF KOTE.	NOT NECESSARY	40.00	-
			1,990.00	1,300.00
GRAND TOTAL			7,172.70	3,631.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/AGI23007062/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.