

ASS. REC. BY:

REF:

LPC / 23007065/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

055 29620

Date / Time

Action / Instruction

Parts estimate not ready, no GIA given

Veh No:

SBS 83998

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Scania

C.G

Colour

Multi Colour

A/C: Insured / Std / NI / NA

Sp. Reading

104PR25

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Y 92K 4X 20001861947

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F:

275 / 70R22.5

R:

C/D

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

11/7/23

D.O.I.

13/7/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

RM O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Soon Bee Vehicle & Bodywork Maintenance

10 Anson Road #33-02 International Plaza Singapore 079903.

Tel: 90036715 Fax: 62256130 Email: soonbee_vehicle@yahoo.com.sg

GST Registration No: M90374725J

Our Ref No. : SB-20837

Date: 11-Jul-23

AMK Workshop.

Foreman: Li Ming

FAX: 64562752

Kennerth CLKK)


98910663

Kennerth Hong @ lkk auto.com

QUOTATION FOR ACCIDENT REPAIR ON BUS NO:

SBS8399Z

We are pleased to offer our best proposal to provide our services of labour for repair of above mentioned vehicle at SBS Transit, Ang Mo Kio Workshop.

1)	Vehicle No : Model :	SBS8399Z SD												
2)	Total Cost :	<table><tr><td>- Material & Parts Cost</td><td>:</td><td></td></tr><tr><td>- Labour Cost</td><td>:</td><td>\$ 750.00</td></tr><tr><td>GST (8%) :</td><td>\$</td><td>60.00</td></tr><tr><td>Total :</td><td>\$</td><td>810.00</td></tr></table>	- Material & Parts Cost	:		- Labour Cost	:	\$ 750.00	GST (8%) :	\$	60.00	Total :	\$	810.00
- Material & Parts Cost	:													
- Labour Cost	:	\$ 750.00												
GST (8%) :	\$	60.00												
Total :	\$	810.00												
	Work Scopes Dismantle and replace front windscreen Repair of dome Repair of driver side body panel Touch up putty and respray  Supply workers for 19 ManHour TERM OF PAYMENT: 30 DAYS UPON DELIVERY OF VEHICLES Vehicle Electric and wiring system not included (B) Materials and Parts: - Supply by SBS Transit C) Mechanical/Engine Effect - NA													

Note: Quotation valid for 1 Month only

This is a computer-generated document. No signature will be required.

97961189

Li Ming