



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD
75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557
ATTN: EILEEN LEE

Ref: CS/INC23007070/Tqy3e2
Date: 02/08/2023
Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GK 8998C	Veh. Inspected	SMW 5687K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1231327-001	Excess (\$)	0.00
Assign From		Assign Date	12/07/2023

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 116D	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA1V72060V725470	Colour	BLACK
Odometer	104566 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/35 R18	BRIDGESTONE	6 mm
L/H Front Tyre	245/35 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	245/35 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	245/35 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/07/2023	Inspect Date / Time	12/07/2023 (03:51 PM)
Survey held at	AP AUTOMOTIVE SERVICES PTE LTD 9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**