

HUI WANG ENTERPRISE PTE LTD

BLK 5 Defu Lane 10, #01-570 Singapore 539186
TEL: 62864541

Date: 22.11.2022

Lonpac Insurance Co Bhd
Motor Claims Department
300 Beach Road #17-04/07 The Concourse
Singapore 199555

Dear Sir/Mdm,

NOTIFICATION OF ACCIDENT

Please be informed that an accident involving my/our vehicle no. PC5801S and vehicle(s) no. PC6235U had taken place at / along Ayer Merbau Rd Twds Jurong Island Expressway on date 16.11.2022 at time 0825hrs.


Kindly let us know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If we do not hear from you within 2 working days, we shall proceed to repair the vehicle without further notice and our client shall claim for the additional loss of use arising from the giving of this notification to you.


Please call Ms Judy Lim at 84686234 to arrange.

Yours sincerely,

PRI

Date / Time	23/11/22 1052pm
Company Name	LKK
Surveyor	Islem
Contact No.	90077659
Signature	

DISMANTLED PARTS

Date / Time	24/11/22 340pm
Surveyor	

AFTER REPAIR

Date / Time	9/12/22
Surveyor	

CERTIFICATE OF INSURANCE

ORIGINAL

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Type of Policy. : BUSES - FLEET
Type of Cover. : Third Party
Certificate No. : D-22099590MFBP/2
Vehicle No / Chassis No : PC5801S / KDH2010180584
Name of Insured : POH TIONG CHOON LOGISTICS LIMITED
Period Of Insurance : 01.07.2022 To 30.06.2023
Insured Estimated Value : 0.00

Excess :

SGD3,500.00 SECTION II
AN ADDITIONAL EXCESS OF SGD2,500.00 ON SECTION II IS IMPOSED ON THOSE
DRIVERS WHO ARE BELOW 23 YEARS OLD AND/OR WHO HAVE LESS THAN 3 YEARS
OF DRIVING EXPERIENCE
ALL EXCESS AMOUNTS ARE SUBJECT TO GST

Authorised Driver*

ANY AUTHORISED DRIVER

Persons or classes of persons entitled to drive*

Any Person provided he is in the Insured's employ and is driving on their order or with their permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitations as to use*

Use only for the carriage of passengers or goods in connection with the Insured's business (as specified in the Schedule).

The Policy does not cover:-

- (1) Use for racing, pacemaking, reliability trial or speed-testing.
- (2) Use whilst drawing a trailer, except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

MS First Capital Insurance Limited
(Approved Insurers)

SUSAN/D0069/MZ601

Issued at Singapore on 30.06.2022



Authorised Signature

HUI WANG ENTERPRISE PTE LTD

BLK 5, DEFU LANE 10, #01-570 / 576, SINGAPORE 539186
TEL: 6286 4541, 6283 0717 | FAX: 6281 0647
EMAIL: Huiwang576@Gmail.com | GST No. 201426468N

TAX INVOICE

To :

Poh Tiong Choon Logistics Limited

Invoice No. : 00000278

Date : 14/2/2023

Reference :

Vehicle Number :

Repair Date :

Attn : Poh Tiong Choon Logistics Limited

QTY	DESCRIPTION	UNIT PRICE	AMOUNT
1	Repair Cost For PC5801S	\$20,000.00	\$20,000.00
INTEREST AT THE RATE 1.5% PER MONTH WILL BE CHARGE ON OVERDUE ACCOUNTS			
Sub-Total			\$20,000.00
GST 8%			\$1,600.00
Total Payable			\$21,600.00

Payment Options

Please note that if you wish to make payment via Bank Transfer or Cheque, indicate the Bank, Amount Transfer & Invoice Number in the email so we are able to confirm that the funds came through. The email can be sent to Accounts@HuiWangEnterprise.com

OCBC SGD Account

Bank Name: Oversea-Chinese Banking Corporation Limited
Account Number: 689 021 566 001
Account Name: Hui Wang Enterprise Private Limited

PayNow



UEN: 201426468N

Received By _____

Issued By _____

*This is computer generated no signature required

E. & O. E.

Impact Analysis Consulting Pte Ltd

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4
#06-46 Synergy @KB
Singapore 417800
Hotline: 6385 1171

Our reference: 22 - 171104

Date: 21/12/2022

INVOICE NO. 171104

Poh Tiong Choon Logistics Limited
c/o Hui Wang Enterprise Pte Ltd
Blk 5 Defu Lane 10
#01-576
Singapore 539186

Registration No. **PC5801S**

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 1,180.00
Total amount			<u>\$ 1,180.00</u>

Please kindly cross all cheques made payable to " Impact Analysis Consulting Pte Ltd ".

We thank you in anticipation for your prompt payment.



L. L. Tan (Ms)
Principal Consultant

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd
www.iaconsultingsg.com

Impact Analysis Consulting Pte Ltd

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4
#06-46 Synergy @KB
Singapore 417800
Hotline: 6385 1171

Our reference: 22 - 171104

Date: 21/12/2022

c/o Hui Wang Enterprise Pte Ltd
Blk 5 Defu Lane 10
#01-576
Singapore 539186

Dear Sirs

RE: Road Traffic Accident on 16/11/2022
Poh Tiong Choon Logistics Limited

In accordance with your instructions received in this office on 22/11/2022, we made arrangements to examine the vehicle on 22/11/2022 at above-mentioned address. The following data was recorded:

Vehicle details


Make	Toyota	Registration	PC5801S
Model	Hiace 3.0 DX Manual	Chassis	KDH2010180584
Colour	White	Gearbox	Manual
Odometer	169487km	Paintwork	Fair
Steering	In order	Brakes	In order
Condition	Fair		

Tyre Depths

Front left	195R15C	75% Toyo
Front right	195R15C	75% Toyo
Rear left	195R15C	75% Toyo
Rear right	195R15C	75% Toyo

Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$20,000.00 and 13 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd
www.iaconsultingsg.com

Our reference: 22 - 171104

Date 21/12/2022

Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items:				
Front bumper	1	deformed	595.00	595.00
Front bumper reinforcement	1	bent	496.00	496.00
Front bumper centre beam	1	bent	264.50	264.50
Front bumper reinforcement bracket @\$89.20	2	rh bent lh refix	178.40	89.20
Front bumper tow cover	1	refix	30.00	0.00
Front bumper side retainer @\$141.00	2	lh broken rh refix	282.00	141.00
Front bumper lower grille	1	deformed.torn	168.60	168.60
Front bumper side grille lh	1	deformed	86.50	86.50
Front windscreen glass	1	cracked	1350.00	1350.00
Front windscreen glass moulding	1	necessary	138.20	138.20
Bonnet	1	distorted	859.90	859.90
Bonnet logo	1	necessary	73.50	73.50
Bonnet hinge @\$68.60	2	twisted	137.20	137.20
Bonnet lock	1	twisted	125.40	125.40
Wiper tank	1	deformed	140.00	140.00
Radiator tank	1	holder torn	250.00	250.00
Front wiper panel	1	distorted	715.00	715.00
Front wiper panel grille garnish	1	deformed.torn	654.00	654.00
Front wiper panel garnish corner lh	1	cut	68.00	68.00
Front wiper linkage	1	refix	375.00	0.00
Front wiper motor	1	refix	486.00	0.00
Front wiper arm lh	1	bent	112.00	112.00
Front wiper blade lh	1	bent	55.00	55.00
Front support panel	1	distorted	667.52	667.52
Front brace panel	1	twisted	109.00	109.00
Head lamp LED @\$2716.00	2	rh cracked.lh crushed	5432.00	5432.00
Head lamp bracket lh	1	broken	20.00	20.00

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd
www.iaconsultingsg.com

Our reference: 22 - 171104

Date 21/12/2022

Radiator grille base	1	deformed.broken	402.00	402.00
Radiator grille panel top	1	deformed.broken	214.70	214.70
Radiator grille panel lower	1	deformed.broken	329.20	329.20
Wiring harness cover box lh	1	broken	212.50	212.50
Front corner panel lh	1	distorted	285.50	285.50
Front corner panel wing mirror assy lh	1	broken	328.20	328.20
Front door side mirror lh	1	cut.cracked	429.60	429.60
Front door lh	1	buckled.warped	1623.20	1623.20
Front door inner trim board lh	1	refix	653.90	0.00
Front door outer moulding lh	1	refix	142.00	0.00
Front door weatherstrip lh	1	refix	196.10	0.00
Front door hinge upper lh	1	bent	95.40	95.40
Front door hinge lower lh	1	bent	95.60	95.60
Front door check lh	1	stiffened	63.20	63.20
Front door lock lh	1	bent.jammed	481.70	481.70
Front widnscreen pillar "A" lh	1	distorted	529.50	529.50
Front door step panel lh	1	distorted	296.80	296.80
Front door step panel inner lh	1	repair.respray	188.50	0.00
Front door step panel garnish lh	1	deformed.torn	179.24	179.24
Air con condenser	1	bent.twisted	974.00	974.00
Radiator	1	twisted	1495.00	1495.00
Radiator cowling	1	torn	375.00	375.00
Inter cooler	1	refix	1450.00	0.00
Inter cooler cowling	1	deformed	182.00	182.00
Inter cooler air guide @\$135.00	2	lh deformed/torn rh refix	270.00	135.00
Air con cooling coil	1	broken	1800.00	1800.00
Air con blower	1	broken	1371.00	1371.00
Dashboard	1	deformed.torn	1355.00	1355.00
			29887.56	26000.86
Percentage discount : 25%			7471.89	6500.22
Sub-Total costs for parts			22415.67	19500.65

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd
www.iaconsultingsg.com

Impact Analysis Consulting Pte Ltd

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4
#06-46 Synergy @KB
Singapore 417800
Hotline: 6385 1171

Our reference: 22 - 171104

Date 21/12/2022

Special Nett Items:

Front bumper clips	set	necessary	40.00	40.00
Radiator grille clips	set	necessary	30.00	30.00
Coolant	1	necessary	50.00	50.00
Front windscreen glass sealant	1	necessary	60.00	60.00
Front door LTA sticker rh/lh	2	necessary	80.00	80.00
Front door inner trim board clips lh	set	necessary	40.00	40.00
ERP unit bracket	1	necessary	30.00	30.00
Front number plate	1	cracked	40.00	40.00
Sub-Total costs for parts			370.00	370.00

Parts Repair

Front door rh - grazed	1	repair.respray	0.00	0.00
Front floor panel lh - bent	1	repair.respray	0.00	0.00
Front chassis member lh	1	repair.respray	0.00	0.00
Front inner panel	1	repair.respray	0.00	0.00
Sub- Total costs			0.00	0.00
Total costs for parts			22785.67	19870.65

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd
www.iaconsultingsg.com

Our reference 22 - 171104

Date 21/12/2022

Page 3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	35	\$ 1,575.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$ 1,400.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 100.00
Remove / replace aircon condenser and refill aircon gas	\$ 45.00	2.5	\$ 112.50
Remove / refix inter cooler and radiator, top up coolant & conduct pressure test	\$ 45.00	3	\$ 135.00
Remove / replace front windscreen glass (2-man job)	\$ 45.00	2.5	\$ 112.50
Transfer of existing lh front door mechanism to new door.	\$ 45.00	2	\$ 90.00
Remove and refix front cabin upholstery to facilitate the repair works	\$ 45.00	1.5	\$ 67.50
To remove and refix dashboard and internal wiring	\$ 45.00	6	\$ 270.00
Specialist charges - Conduct front chassis alignment	-	-	\$ 250.00
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$ 45.00	1	\$ 45.00
Total labour cost			\$ 4,157.50

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Subsidiaries of Impact Analysis:

- Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd
- www.laconsultingsg.com

Our reference 22 - 171104

Date 21/12/2022

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment <i>(See section A)</i>		\$19,870.65	
Lump Sum		\$3,974.13	
Further discount	20%		
Recommended cost of parts		\$15,896.52	(1)
Labour Cost Calculation <i>(See section B)</i>		\$4,157.50	(2)
Total Repair Cost <i>(Round off to hundred)</i>		\$20,000.00	(1) + (2)

We would recommend a sum of **\$20,000.00** and **13** working days for repair.
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.


Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
B.Eng. (Hons, NUS)
Diploma.Mechanical Engineering
NTC-2 Automovite Technology
Sr.MIES, Institution of Engineers, Singapore (#20100091)
MATAI, Maryland Association of Traffic Accident Investigators
IAARS, International Association of Accident Reconstruction Specialists
PMC of Singapore Business Advisors & Consultants Council

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd
www.iaconsultingsg.com

