### **HUI WANG ENTERPRISE PTE LTD**

BLK 5 Defu Lane 10, #01-570 Singapore 539186 TEL: 62864541

Date: 22.11.2022

Lonpac Insurance Co Bhd Motor Claims Department 300 Beach Road #17-04/07 The Concourse Singapore 199555

Dear Sir/Mdm,

### **NOTIFICATION OF ACCIDENT**

Please be informed that an accident involving my/our vehicle no. <u>PC5801S</u> and vehicle(s) no. <u>PC6235U</u> had taken place at / along <u>Ayer Merbau Rd Twds Jurong Island Expressway</u> on date <u>16.11.2022</u> at time <u>0825hrs</u>.

Kindly let us know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If we do not hear from you within 2 working days, we shall proceed to repair the vehicle without further notice and our client shall claim for the additional loss of use arising from the giving of this notification to you.

Please call Ms Judy Lim at 84686234 to arrange.

Yours sincerely,

PRI

23/11/22 1052 pt
LKK
1,Cm
90077659
8/

#### DISMANTLED PARTS

Date / Time	24/11/22 3	Lopm
Surveyor	1/m	ן '
		_

#### AFTER REPAIR

Date / Time	9(12/2)	
Surveyor		



MS First Capital Insurance Limited Co. Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

#### CERTIFICATE OF INSURANCE

**ORIGINAL** 

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Parly Risks) Rules, 1959 (Malaysia)

Type of Policy.

: BUSES - FLEET

Type of Cover.

: Third Party

Certificate No.

: D-22099590MFBP/2

Vehicle No / Chassis No

: PC5801S / KDH2010180584

Name of Insured

: POH TIONG CHOON LOGISTICS LIMITED

Period Of Insurance

: 01.07.2022 To 30.06.2023

Insured Estimated Value

: 0.00

Excess:

AN ADDITIONAL EXCESS OF SGD2,500.00 ON SECTION II IS IMPOSED ON THOSE DRIVERS WHO ARE BELOW 23 YEARS OLD AND/OR WHO HAVE LESS THAN 3 YEARS OF DRIVING EXPERIENCE ALL EXCESS AMOUNTS ARE SUBJECT TO GST

Authorised Driver\* ANY AUTHORISED DRIVER

Persons or classes of persons entitled to drive\*

Any Person provided he is in the Insured's employ and is driving on their order or with their permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor

Use only for the carriage of passengers or goods in connection with the Insured's business (as specified in the Schedule).

The Policy does not cover:-

(1) Use for racing, pacemaking, reliability trial or speed-testing.

(2) Use whilst drawing a trailer, except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

\*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

> MS First Capital Insurance Limited (Approved Insurers)

> > Pic.

SUSAN/D0069/MZ601

Issued at Singapore on 30.06.2022

Authorised Signature

### HUI WANG ENTERPRISE PTE LTD

BLK 5, DEFU LANE 10, #01-570 / 576, SINGAPORE 539186 TEL: 6286 4541, 6283 0717 | FAX: 6281 0647 EMAIL: Huiwang576@Gmail.com | GST No. 201426468N

To:

Poh Tiong Choon Logistics Limited

**TAX INVOICE** 

Invoice No.

: 00000278

Date

: 14/2/2023

Reference

Vehicle Number

Repair Date

Attn: Poh Tiong Choon Logistics Limited

QTY	DESCRIPTION	UNIT PRICE	AMOUNT
1	Repair Cost For PC5801S	\$20,000.00	#20,000.00
INTERES	T AT THE RATE 1.5% PER MONTH WILL BE CHARGE ON OVERDUE ACCOUNTS	Sub-Total GST 8% Total Payable	\$20,000.00 \$1,600.00 <b>\$21,600.0</b> 0

#### **Payment Options**

Please note that if you wish to make payment via Bank Transfer or Cheque, indicate the Bank, Amount Transfer & Invoice Number in the email so we are able to confirm that the funds came through. The email can be sent to Accounts@HuiWangEnterprise.com

#### **OCBC SGD Account**

Bank Name: Oversea-Chinese Banking Corporation Limited Account Number: 689 021 566 001

Account Name: Hui Wang Enterprise Private Limited



UEN: 201426468N

Received By	Issued By

Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

22 - 171104

Date:

21/12/2022

**INVOICE NO. 171104** 

**Poh Tiong Choon Logistics Limited** c/o Hui Wang Enterprise Pte Ltd Blk 5 Defu Lane 10 #01-576 Singapore 539186

Registration No.

PC5801S

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 1,180.00
		Total amount	\$ 1,180.00

Please kindly cross all cheques made payable to "Impact Analysis Consulting Pte Ltd".

We thank you in anticipation for your prompt payment.

L. L. Tan (Ms) Principal Consultant

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

Our reference:

22 - 171104

Date:

21/12/2022

c/o Hui Wang Enterprise Pte Ltd Blk 5 Defu Lane 10 #01-576 Singapore 539186

**Dear Sirs** 

RE:

Road Traffic Accident on 16/11/2022
Poh Tiong Choon Logistics Limited

In accordance with your instructions received in this office on

22/11/2022 , we made arrangements to

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB

Singapore 417800

Hotline: 6385 1171

examine the vehicle on

22/11/2022

at above-mentioned address. The following data was

recorded:

#### Vehicle details


Make	Toyota	Registration	PC5801S
Model	Hiace 3.0 DX Manual	Chassis	KDH2010180584
Colour	White	Gearbox	Manual
Odometer	169487km	Paintwork	Fair
Steering	In order	Brakes	In order
Condition	Fair	******************************	

#### **Tyre Depths**

Front left	195R15C	75% Toyo
Front right	195R15C	75% Toyo
Rear left	195R15C	75% Toyo
Rear right	195R15C	75% Toyo

Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

#### Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$20,000.00 and 13 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis:

 Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd www.iaconsultingsg.com

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

22 - 171104

Date

21/12/2022

Page

2

### **Section A: Damaged Parts Assessment**

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
<u>List Items:</u>				
Front bumper	1	deformed	595.00	595.00
Front bumper reinforcement	1	bent	496.00	496.00
Front bumper centre beam	1	bent	264.50	264.50
Front bumper reinforcement bracket@\$89.20	2	rh bent lh refix	178.40	89.20
Front bumper tow cover	1	refix	30.00	0.00
Front bumper side retainer @\$141.00	2	lh broken rh refix	282.00	141.00
Front bumper lower grille	1	deformed.torn	168.60	168.60
Front bumper side grille Ih	1	deformed	86.50	86.50
Front windscreen glass	1	cracked	1350.00	1350.00
Front windscreen glass moulding	1	necessary	138.20	138.20
Bonnet	1	distorted	859.90	859.90
Bonnet logo	1	necessary	73.50	73.50
Bonnet hinge @\$68.60	2	twisted	137.20	137.20
Bonnet lock	1	twisted	125.40	125.40
Wiper tank	1	deformed	140.00	140.00
Radiator tank	1	holder torn	250.00	250.00
Front wiper panel	1	distorted	715.00	715.00
Front wiper panel grille garnish	1	deformed.torn	654.00	654.00
Front wiper panel garnish corner lh	1	cut	68.00	68.00
Front wiper linkage	1	refix	375.00	0.00
Front wiper motor	1	refix	486.00	0.00
Front wiper arm Ih	1	bent	112.00	112.00
Front wiper blade lh	1	bent	55.00	55.00
Front support panel	1	distorted	667.52	667.52
Front brace panel	1	twisted	109.00	109.00
Head lamp LED @\$2716.00	2	rh cracked.lh crushed	5432.00	5432.00
Head lamp bracket Ih	1	broken	20.00	20.00

Subsidiaries of Impact Analysis:

<sup>•</sup> Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd www.iaconsultingsg.com

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

22 - 171104

Date

21/12/2022

tal costs for parts 22415.67	19500.65
ount: 25% 7471.89	6500.22
29887.56	26000.86
1 deformed.torn1355.00	1355.00
1 broken 1371.00	1371.00
1 broken 1800.00	1800.00
2 Ih deformed/torn rh refix 270.00	135.00
1 deformed 182.00	182.00
1 refix 1450.00	0.00
1 torn 375.00	375.00
1 twisted 1495.00	1495.00
1 bent.twisted 974.00	974.00
1 deformed.torn 179.24	179.24
1 repair.respray 188.50	0.00
1 distorted 296.80	296.80
1 distorted 529.50	529.50
1 bent.jammed 481.70	481.70
1 stiffened 63.20	63.20
1 bent 95.60	95.60
1 bent 95.40	95.40
1 refix 196.10	0.00
1 refix 142.00	0.00
1 refix 653.90	0.00
1 buckled.warped 1623.20	1623.20
1 cut.cracked 429.60	429.60
1 broken 328.20	328.20
1 distorted 285.50	285.50
1 broken 212.50	212.50
1 deformed.broken 329.20	329.20
1 deformed.broken 214.70	214.70
1 deformed.broken 402.00	402.00

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd www.iaconsultingsg.com

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171** 

Our reference:

22 - 171104

Date

21/12/2022

Special Nett Items:			40.00	
Front bumper clips	set	necessary	40.00	40.00
Radiator grille clips	set	necessary	30.00	30.00
Coolant	1	necessary	50.00	50.00
Front windscreen glass sealant	1	necessary	60.00	60.00
Front door LTA sticker rh/lh	2	necessary	80.00	80.00
Front door inner trim board clips Ih	set	necessary	40.00	40.00
ERP unit bracket	1	necessary	30.00	30.00
Front number plate	1	cracked	40.00	40.00
	Sub-Total costs	s for parts	370.00	370.00
Parts Repair				
Front door rh - grazed	1	repair.respray	0.00	0.00
Front floor panel Ih - bent	1	repair.respray	0.00	0.00
Front chassis member Ih	1	repair.respray	0.00	0.00
Front inner panel	1	repair.respray	0.00	0.00
•	Sub- Total costs		0.00	0.00
	Total costs fo	or parts	22785.67	19870.65

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference

22 - 171104

Date

21/12/2022

Page

3

#### **Section B: Labour Cost Calculation**

	Но	urly rate	Manhr. Req.		Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	45.00	35	\$	1,575.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.		Sub-contract work.			1,400.00
Apply rust proofing on the adjacent panels.		Sub-contract work.			100.00
Remove / replace aircon condenser and refill aircon gas	\$	45.00	2.5	\$	112.50
Remove / refix inter cooler and radiator, top up coolant & conduct pressure test	\$	45.00	3	\$	135.00
Remove / replace front windscreen glass (2-man job)	\$	45.00	2.5	\$	112.50
Transfer of existing Ih front door mechanism to new door.	\$	45.00	2	\$	90.00
Remove and refix front cabin upholstery to facilitate the repair works	\$	45.00	1.5	\$	67.50
To remove and refix dashboard and internal wiring	\$	45.00	6	\$	270.00
Specialist charges - Conduct front chassis alignment			_	\$	250.00
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$	45.00	1	\$	45.00
		Total la	bour cost	\$	4,157.50

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd www.laconsultingsg.com

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171** 

Our reference

22 - 171104

Date

21/12/2022

### **Section C: Summary Table of Total Repair Cost**

Description		Cost	
Asse	ged Parts ssment ection A)	\$19,870.65	
Lump Sum		62.074.42	
Further discount	20%	\$3,974.13	
Recommended cost of parts		\$15,896.52	(1)
	ection B)	\$4,157.50	(2)
Total Repair Cost (Round off to hundred)		\$20,000.00	(1) + (2)

We would recommend a sum of	\$20,000.00	and	13	working days for repair.
No further items will be approved w	ithout our expresse	ed written agreeme	ent. Any signific	cant additional
items will be subject to a supplemen	tary report.			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

