

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2002648411-01	Date of Loss:	08/07/2023
Vehicle Reg. No.:	SLT4370H	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM GAY PIOW	Contact No:	+6590214133
Driver:	LIM GAY PIOW		
Make/Model:	MAZDA 2, 1.5 HATCHBACK L SP.6EAT (A)	Vehicle Reg. Date:	30/10/2017
Vehicle Colour:	Blue	Chassis No:	JM6DJ2HAA01200164
Engine No:	P520479680		
Odometer:	117292 KM		<i>NOT NOTHING 11 Day & Recovery After Paint</i>
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18 9 days		
Present Location:	DING AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	16,291.00
Miscellaneous Items	435.00
Labour	3,210.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	19,936.00
+ GST 8.00% (S\$)	1,594.88
Nett Amount (S\$)	21,530.88

This claim is handled by: **HENRY LEE YOON SANG**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jul 2023)
 Parts: 144 MAZDA 2 1.5 HATCHBACK L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ding Auto Pte Ltd/SLT4370H/12/07/2023 11:27
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount		
1	1		*FRONT BUMPER	0.00	0.00	By *420.00 F	—	
2	1		*FRONT BUMPER RETAINER RH	0.00	0.00	DIT *20.00 F	—	
3	1		*FRONT BUMPER RETAINER LH	0.00	0.00	DIT *20.00 F	—	
4	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*380.00 F	7	
5	1		*FRONT BUMPER FOAM	0.00	0.00	*95.00 F	7	
6	1		*FRONT BUMPER LOWER GARNISH	0.00	0.00	Sn *105.00 F	X	
7	1		*FRONT BUMPER SIDE COVER RH	0.00	0.00	Sn *90.00 F	X	
8	1		*FRONT BUMPER SIDE COVER LH	0.00	0.00	Sn *90.00 F	X	
9	1		*FRONT BUMPER TOW CAP	0.00	0.00	na *25.00 F	—	
10	1		*BONNET	0.00	0.00	Bu *750.00 F	—	
11	1		*BONNET HINGE RH	0.00	0.00	*45.00 F	—	
12	1		*BONNET HINGE LH	0.00	0.00	*45.00 F	—	
13	1		*BONNET LOCK	0.00	0.00	DIT *110.00 F	—	
14	1		*BONNET STAND	0.00	0.00	Sn *35.00 F	X	
15	1		*FRONT GRILLE BASE	0.00	0.00	CM *150.00 F	—	
16	1		*FRONT GRILLE CHROME TRIM RH	0.00	0.00	CM *105.00 F	—	
17	1		*FRONT GRILLE CHROME TRIM LH	0.00	0.00	CM *105.00 F	—	
18	1		*FRONT GRILLE UPPER PANEL	0.00	0.00	CM *185.00 F	7	
19	1		*FRONT GRILLE BADGE	0.00	0.00	na *25.00 F	—	
20	1		*FRONT LOWER GRILLE	0.00	0.00	*120.00 F	7	
21	1		*FRONT SUPPORT PANEL CPL	0.00	0.00	*400.00 F	7	
22	1		*FRONT PANEL UPPER GARNISH	0.00	0.00	*95.00 F	7	
23	1		*FRONT FENDER RH	0.00	0.00	Bu *220.00 F	—	
24	1		*FRONT FENDER LH	0.00	0.00	Bu *220.00 F	—	
25	1		*FRONT FENDER INNER SHIELD RH	0.00	0.00	Sn *90.00 F	X	
26	1		*FRONT FENDER INNER SHIELD LH	0.00	0.00	Sn *90.00 F	X	
27	1		*WIPER GARNISH	0.00	0.00	na *180.00 F	X	
28	1		*WIPER GARNISH END COVER RH	0.00	0.00	Sn *20.00 F	X	
29	1		*WIPER GARNISH END COVER LH	0.00	0.00	Sn *20.00 F	X	
30	1		*HEADLAMP ASSY RH					
31	1		*HEADLAMP ASSY LH	mtj CM	0.00	0.00	*580.00 F	—
32	1		*HEADLAMP BRACKET RH	4 4	0.00	0.00	*30.00 F	7
33	1		*HEADLAMP BRACKET LH		0.00	0.00	*30.00 F	7
34	1		*RADIATOR ASSY		0.00	0.00	*550.00 F	7
35	1		*RADIATOR AIR GUARD RH		0.00	0.00	*35.00 F	7
36	1		*RADIATOR AIR GUARD LH		0.00	0.00	*35.00 F	7
37	1		*CONDENSOR ASSY		0.00	0.00	*880.00 F	7
38	1		*FAN COWLING UNIT COMPLETE		0.00	0.00	*680.00 F	7
39	1		*A/COND SUCTION HOSE		0.00	0.00	*180.00 F	7
40	1		*A/COND DISCHARGE HOSE		0.00	0.00	*130.00 F	7
41	1		*WASHER TANK		0.00	0.00	Sn *60.00 F	X
42	1		*EXPANSION TANK		0.00	0.00	*70.00 F	7
43	1		*AIR CLEANER HOUSING CPL		0.00	0.00	*120.00 F	7
44	1		*AIR DUCT		0.00	0.00	*85.00 F	7
45	1		*AIR HOSE		0.00	0.00	*55.00 F	7
46	1		*HORN - LOW PITCH		0.00	0.00	*90.00 F	7
47	1		*ENGINE LOWER COVER		0.00	0.00	Sn *115.00 F	X

48	1	*DASHBOARD ASSY	0.00	0.00	7/	*1,150.00 F
49	1	*AIRBAG - DRIVER	0.00	0.00	Bury	*1,450.00 F
50	1	*AIRBAG - PASSENGER	0.00	0.00	7/	*1,550.00 F
51	1	*AIRBAG - ECU	0.00	0.00	7/	*850.00 F
52	1	*SEAT BELT ASSY RH	0.00	0.00	7/	*550.00 F
53	1	*SEAT BELT ASSY LH	0.00	0.00	7/	*550.00 F
54	1	*STEERING - SPRING CLOCK COLUMN	0.00	0.00	7/	*150.00 F

1
1
1
1
1
1
1

F=Franchise part.

Sub Total (S\$)	14,810.00
+ Margin on L,N Items 10.00% (S\$)	1,481.00
Total Parts (S\$)	16,291.00

Ding Auto Pte Ltd/SLT4370H/12/07/2023 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	AIRBAG ECU - DIAGNOSTIC & RE-SETTING	250.00
2	1	FRT BUMPER, GRILLE, INNER SHIELD & GARNISH/PANEL - CLIPS	150.00
3	1	FRT NUMBER PLATE & FRAME	35.00
Sub Total (S\$)			435.00

200
600
CM

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,200.00
2	SPRAY PAINT - FRT BUMPER, BONNET, FRT FENDER X2, FRT DOOR X2 & SUPPORT PANEL	New	1,200.00
3	REMOVE & INSTALL - DASHBOARD COMPONENTS	New	250.00
4	REMOVE & INSTALL - SEAT BELT COMPONENTS	New	150.00
5	REMOVE & INSTALL - RADIATOR & CONDENSOR COMPONENTS	New	150.00
6	ALIGN HEADLAMP/SENSOR & TEST WIRING	New	100.00
7	REFILL - RADIATOR COOLANT	New	80.00
8	REFILL - AIR COND GAS	New	80.00
Gross Labour Cost (S\$)			3,210.00

600
800
✓
100
100
20
50
X

Ding Auto Pte Ltd/SLT4370H/12/07/2023 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: