



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 22002-06/MY / 2022
Date of Report : 24 Jun 2022

Chow Weng Hon Charles
No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 30 May 2022

Workshop Address : Bluwel Automotive Service Pte Ltd
No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

As per your instruction dated **1 Jun 2022** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SKB 1761 P**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SKB 1761 P	Engine No	: CZE388134
Model	: Volkswagen Tiguan	Mileage	: 78447
Year / Capacity	: 2018/1395	Colour	: Black
Chassis No	: WVGZZZ5NZJW951032		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 235/55 R18	Pirelli	5.00	mm	Sport
REAR O/S	: 235/55 R18	Yohohama	5.00	mm	Sport
FRONT N/S	: 235/55 R18	Pirelli	5.00	mm	Sport
REAR N/S	: 235/55 R18	Yohahama	5.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 7 working days to complete.
5. Enclosed number of photograph : 106 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SKB 1761 P**
 Report No: **TP/ 22002-06/MY / 2022**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear tailgate	Damage	\$ 1958.50	\$ 1958.50
1	Rear tailgate inner board	Intact	\$ 461.50	\$
1	Rear tailgate lock	Intact	\$ 285.00	\$
1	Rear tailgate logo	Necessary	\$ 116.50	\$ 116.50
1	Rear tailgate rubber	Necessary	\$ 155.00	\$ 155.00
1	Rear tailgate 'TIGUAN' emblem	Necessary	\$ 82.50	\$ 82.50
1	Rear taillamp	Damage	\$ 386.50	\$ 386.50
1	Rear end panel	Damage	\$ 665.00	\$ 665.00
1	Rear end panel inner garnish	Damage	\$ 266.00	\$ 266.00
1	Rear top bumper	Damage	\$ 1325.00	\$ 1325.00
1	Rear bumper centre guide	Damage	\$ 135.00	\$ 135.00
1	Rear bumper lower extension	Damage	\$ 865.00	\$ 865.00
1	Rear bumper reflector	Damage	\$ 89.50	\$ 89.50
1	Rear bumper reinforcement	Damage	\$ 712.50	\$ 712.50
1	Rear bumper side retainer	Damage	\$ 137.00	\$ 137.00
2	Rear bumper small reflectors	Intact	\$ 98.00	\$
2	Rear bumper sensors	Damage	\$ 452.00	\$ 452.00
1	Rear bumper tow cover	Damage	\$ 42.00	\$ 42.00
1	Rear fender	Repair	\$ 2045.00	\$
			<u>\$ 10277.50</u>	<u>\$ 7388.00</u>
	Discount	10.0%	<u>\$ 1027.75</u>	<u>\$ 738.80</u>
			<u>\$ 9249.75</u>	<u>\$ 6649.20</u>
<u>Special Nett Items</u>				
1	Rear windscreen sealant	Necessary	\$ 80.00	\$ 60.00
1	Rear windscreen seal	Necessary	\$ 85.00	\$ 85.00
1	Rear number plate	Damage	\$ 50.00	\$ 50.00
			<u>\$ 215.00</u>	<u>\$ 195.00</u>

Spare Parts Total \$ 9464.75 \$ 6844.20

Vehicle No: **SKB 1761 P**
Report No: **TP/ 22002-06/MY / 2022**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 9464.75	\$ 6844.20
1	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 60.00	\$ 40.00
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 150.00	\$ 80.00
3	To remove and refit rear bumper sensor.	\$ 180.00	\$ 120.00
4	To remove and refit rear windscreen glass.	\$ 200.00	\$ 120.00
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 980.00	\$ 660.00
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1200.00	\$ 880.00
7	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 60.00
Total		\$ 12334.75	\$ 8804.20

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 7000.00

SDLS: SEVEN THOUSAND ONLY


Qualified Appraiser







































































