

# CL APPRAISER PTE LTD

Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416  
 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783  
 Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Lim Kok Choon  
 C/o: Trident Auto Service Centre Pte Ltd  
 8 Kaki Bukit Ave 4  
 #02-42 Premier @ Kaki Bukit, Singapore 415875

Date : 12 June 2023  
 Our ref : TRI/06/2301/TP

Accident Date : 20 May 2023  
 Inspection Date : 6 June 2023  
 Repairer Name : Trident Auto Service Centre Pte Ltd  
 8 Kaki Bukit Ave 4  
 #02-42 Premier @ Kaki Bukit, Singapore 415875

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

|                 |                      |                 |                  |
|-----------------|----------------------|-----------------|------------------|
| Registration No | : SKR 3529 Y         | Year / Capacity | : 2015 / 1595 cc |
| Make / Model    | : Mercedes Benz C180 | Colour          | : Silver         |
| Chassis No      | : WDD2050402R042685  | Mileage         | : 133881         |
| Engine No       | : 27491030333366     |                 |                  |

### CONDITION OF TYRES

|                | Make      | Size       | Thread Balance | Rim   |
|----------------|-----------|------------|----------------|-------|
| Front Nearside | : Pirelli | 225/50 R17 | 5 mm           | Sport |
| Front Offside  | : Pirelli | 225/50 R17 | 5 mm           | Sport |
| Rear Nearside  | : Pirelli | 225/50 R17 | 5 mm           | Sport |
| Rear Offside   | : Pirelli | 225/50 R17 | 5 mm           | Sport |

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.  
 (Details refer to the photographs attached)

Enclosed number of photographs: **81** copies

### REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$7,600.00** on a contractual basis.

Under normal circumstances, the repair period would be about 5 (Five) working days.

# **S&C L APPRAISER PTE LTD**

Vehicle Registration No.: SKR 3529 Y

Our Ref No.:

TRI/06/2301/TP

| Qty | Description | Conditions | Repairer's Estimate | Revised Amount |
|-----|-------------|------------|---------------------|----------------|
|-----|-------------|------------|---------------------|----------------|

## SPARE PARTS - LIST ITEMS

|                                |  |           |                          |           |                              |
|--------------------------------|--|-----------|--------------------------|-----------|------------------------------|
| 1                              | Rear boot lid                              | Repair    | \$ 2,200.00              | <i>xR</i> |                              |
| 1                              | Rear boot rubber                           | Intact    | \$ 185.00                | <i>xm</i> |                              |
| 1                              | Rear boot logo                             | Necessary | \$ 78.00                 | \$        | 78.00                        |
| 1                              | Rear boot "C180" emblem                    | Necessary | \$ 62.00                 | \$        | 62.00                        |
| 1                              | Rear boot "C&C" emblem                     | Necessary | \$ 68.00                 | \$        | 68.00                        |
| 1                              | Rear end panel                             | Damage    | \$ 1,248.00              | \$        | 1,248.00 <i>Rx</i>           |
| 1                              | Rear bumper                                | Damage    | \$ 2,085.00              | \$        | 2,085.00 <i>1899.21</i>      |
| 2                              | Rear bumper side guides                    | Damage    | \$ 124.00                | \$        | 124.00                       |
| 1                              | Rear bumper lower chrome moulding          | Damage    | \$ 480.00                | \$        | 480.00 <i>380</i>            |
| 1                              | Rear bumper reinforcement                  | Damage    | \$ 817.00                | \$        | 817.00 <i>xm</i>             |
| 2                              | Rear bumper side retainers                 | Necessary | \$ 170.00                | \$        | 170.00                       |
| 1                              | Rear bumper under cover                    | Damage    | \$ 285.00                | \$        | 285.00                       |
| 1                              | Rear bumper lower diffuser                 | Damage    | \$ 1,280.00              | \$        | 1,280.00 <i>645.11</i>       |
| 2                              | Rear bumper PDC sensors <i>\$ 225 each</i> | Damage    | \$ 770.00                | \$        | 770.00 <i>450</i>            |
| 1                              | Rear bumper tow hook cover                 | Damage    | \$ 28.00                 | \$        | 28.00                        |
| 1                              | Rear bumper inner frame pad                | Damage    | \$ 285.00                | \$        | 285.00                       |
| 1                              | Control module for park assistant kit      | Damage    | \$ 345.00                | \$        | 345.00                       |
|                                |  |           | \$ 10,510.00             | \$        | 8,125.00 <i>4819.32</i>      |
|                                |  |           | <i>Less 5%</i> \$ 525.50 | \$        | 406.25                       |
| <b>Total Cost - List Items</b> |  |           | \$ 9,984.50              | \$        | 7,718.75 <i>10% - 437.39</i> |

## SPECIAL NETT ITEMS

|  |                          |           |          |    |                   |
|--|--------------------------|-----------|----------|----|-------------------|
| 1                                      | Rear bumper clip (1 set) | Necessary | \$ 80.00 | \$ | 80.00 <i>4000</i> |
| <b>Total Cost - Special Nett items</b> |                          |           | \$ 80.00 | \$ | 80.00             |

**Total cost of parts**

|              |             |
|--------------|-------------|
| \$ 10,064.50 | \$ 7,798.75 |
|--------------|-------------|

# **LCL APPRAISER PTE LTD**

Vehicle Registration No.: SKR 3529 Y

Our Ref No.:

TRI/06/2301/TP

| S/No | Description                    | Repairer's Estimate | Revised Amount     |
|------|--------------------------------|---------------------|--------------------|
|      | <b>Total cost of parts c/f</b> | <b>\$ 10,064.50</b> | <b>\$ 7,798.75</b> |

## LABOUR

|   |  |             |                          |
|---|--|-------------|--------------------------|
| 1 | To remove and refit inner garnishes, inner trim to assist repair.  | \$ 150.00   | \$ 80.00 <sup>60</sup>   |
| 2 | To remove and refit rear reverse sensor.   | \$ 120.00   | \$ 120.00 <sup>40</sup>  |
| 3 | To apply undercoating on repaired and replaced panel.  | \$ 100.00   | \$ 90.00 <sup>30</sup>   |
| 4 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident. | \$ 1,000.00 | \$ 750.00 <sup>600</sup> |
| 5 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.  | \$ 850.00   | \$ 660.00                |

1390

## **GRAND TOTAL**

|                     |                    |
|---------------------|--------------------|
| <b>\$ 12,284.50</b> | <b>\$ 9,498.75</b> |
|---------------------|--------------------|

4337.39  
 40  
 1390  
 -----  
 5767.39  
 4584600  
 0.5 days

Vehicle Registration No.: SKR 3529 Y

Our Ref No.:

TRI/06/2301/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,600.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be void.

**Disclaimer**

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

**C L APPRAISER PTE LTD**

  
\_\_\_\_\_  
Cheong K. H.

Automotive Appraiser