



Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Lim Kok Choon
C/o: Trident Auto Service Centre Pte Ltd
8 Kaki Bukit Ave 4
#02-42 Premier @ Kaki Bukit, Singapore 415875

Date : 12 June 2023
Our ref : TRI/06/2301/TP

Accident Date : 20 May 2023
Inspection Date : 6 June 2023
Repairer Name : Trident Auto Service Centre Pte Ltd
8 Kaki Bukit Ave 4
#02-42 Premier @ Kaki Bukit, Singapore 415875

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No	: SKR 3529 Y	Year / Capacity	: 2015 / 1595 cc
Make / Model	: Mercedes Benz C180	Colour	: Silver
Chassis No	: WDD2050402R042685	Mileage	: 133881
Engine No	: 27491030333366		

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Pirelli	225/50 R17	5 mm	Sport
Front Offside	: Pirelli	225/50 R17	5 mm	Sport
Rear Nearside	: Pirelli	225/50 R17	5 mm	Sport
Rear Offside	: Pirelli	225/50 R17	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: **81** copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$7,600.00** on a contractual basis.

Under normal circumstances, the repair period would be about 5 (Five) working days.

Vehicle Registration No.: SKR 3529 Y

Our Ref No.:

TRI/06/2301/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear boot lid	Repair	\$ 2,200.00	
1	Rear boot rubber	Intact	\$ 185.00	
1	Rear boot logo	Necessary	\$ 78.00	\$ 78.00
1	Rear boot "C180" emblem	Necessary	\$ 62.00	\$ 62.00
1	Rear boot "C&C" emblem	Necessary	\$ 68.00	\$ 68.00
1	Rear end panel	Damage	\$ 1,248.00	\$ 1,248.00
1	Rear bumper	Damage	\$ 2,085.00	\$ 2,085.00
2	Rear bumper side guides	Damage	\$ 124.00	\$ 124.00
1	Rear bumper lower chrome moulding	Damage	\$ 480.00	\$ 480.00
1	Rear bumper reinforcement	Damage	\$ 817.00	\$ 817.00
2	Rear bumper side retainers	Necessary	\$ 170.00	\$ 170.00
1	Rear bumper under cover	Damage	\$ 285.00	\$ 285.00
1	Rear bumper lower diffuser	Damage	\$ 1,280.00	\$ 1,280.00
2	Rear bumper PDC sensors	Damage	\$ 770.00	\$ 770.00
1	Rear bumper tow hook cover	Damage	\$ 28.00	\$ 28.00
1	Rear bumper inner frame pad	Damage	\$ 285.00	\$ 285.00
1	Control module for park assistant kit	Damage	\$ 345.00	\$ 345.00
			\$ 10,510.00	\$ 8,125.00
			<i>Less 5%</i>	<i>\$ 406.25</i>
Total Cost - List Items			\$ 9,984.50	\$ 7,718.75

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	Necessary	\$ 80.00	\$ 80.00
Total Cost - Special Nett items			\$ 80.00	\$ 80.00

Total cost of parts
\$ 10,064.50 \$ 7,798.75

Vehicle Registration No.: SKR 3529 Y

Our Ref No.:

TRI/06/2301/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 10,064.50	\$ 7,798.75
<u>LABOUR</u>			
1	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 80.00
2	To remove and refit rear reverse sensor.	\$ 120.00	\$ 120.00
3	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 90.00
4	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,000.00	\$ 750.00
5	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 850.00	\$ 660.00
GRAND TOTAL		\$ 12,284.50	\$ 9,498.75

Vehicle Registration No.: SKR 3529 Y

Our Ref No.: TRI/06/2301/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,600.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H.
Automotive Appraiser

